



Product End-of-Life (EOL) Notification

AFFECTED PART NUMBER(S): LZC-03MC00 LZC-83MC00	EOL No. <p style="text-align: center;">23</p>
PART DESCRIPTION: LZC RGB Emitter LZC RGB Emitter on 3-Ch MCPCB	DATE: <p style="text-align: center;">7/1/2016</p>
RECOMMENDED REPLACEMENT PART NUMBER(S): LZC-03MD07/ LZC-03MA07: LZC RGBW/ RGBA Emitter LZC-B3MD07/ LZC-B3MA07: LZC RGBW/ RGBA Emitter on 4-Ch MCPCB	
REASON FOR EOL: Market demand have shifted from 3-color LED emitter to 4-or-more-color LED emitter.	
LAST ORDER DATE: <p style="text-align: center;">7/31/2016</p>	LAST SHIPMENT DATE: <p style="text-align: center;">8/31/2016</p>
DISPOSITION OF EXISTING INVENTORY: LED Engin will not support this product after 8/31/2016	
NOTE: <p style="text-align: center;">N/A</p>	
CONTACT PERSON: Erin Tjahjono Product Manager 651 River Oaks Parkway San Jose, CA 95134 etjahjono@ledengin.com	