

Light is OSRAM


Product Discontinuation (acc. JEDEC J-STD-048)  
OS-PD-2017-041

7/3/2017

---

<b>Last order:</b>	7/30/2017
<b>Last delivery:</b>	8/30/2017
<b>Reason:</b>	Product streamline and consolidation.

---



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Brand	Device	Datasheet Ordering Code	Function	Brand
GW SBLMA3.EM-HR-XX33-L1-65-R18-XX	Q65112A0903	LED	DURIS S2	No replacement			
GW SBLMA3.EM-HR-XX35-L1-65-R18-XX	Q65112A0902	LED	DURIS S2	No replacement			
GW SBLMA3.EM-HDHR-XX37-L1-65-R18-XX	Q65112A0906	LED	DURIS S2	No replacement			
GW SBLMA3.EM-HR-XX31-L1-65-R18-XX	Q65112A0907	LED	DURIS S2	No replacement			

# Products Affected by Product Discontinuation Notification

**Number:** OS-PD-2017-041

**Name:** Discontinuation for Product Streamline and Consolidation

**Release Date:** 7/3/2017

**Last Order:** 7/30/2017

**Last Delivery:** 8/30/2017

**DISCONTINUED**

**NEW (REPLACEMENT)**

<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>	<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>
GW SBLMA3	Q65112A0902	GW SBLMA3.EM-HR-XX35-L1-65-R18-XX	GW SBLMA3.EM-HR-XX35-L1-XX	No replacem		No replacement	
GW SBLMA3	Q65112A0903	GW SBLMA3.EM-HR-XX33-L1-65-R18-XX	GW SBLMA3.EM-HR-XX33-L1-XX	No replacem		No replacement	
GW SBLMA3	Q65112A0906	GW SBLMA3.EM-HDHR-XX37-L1-65-R18-XX	GW SBLMA3.EM-HDHR-XX37-L1-XX	No replacem		No replacement	
GW SBLMA3	Q65112A0907	GW SBLMA3.EM-HR-XX31-L1-65-R18-XX	GW SBLMA3.EM-HR-XX31-L1-XX	No replacem		No replacement	