



Product Change Notification

Date Issued :	April 29, 2022	PCN Number :	511885
Reason for Change :	Change to Product		
Description of Change :	This notification is to inform that as the Pre-tinning Process has become highly Instable and inefficient to meet conformance the product has been reevaluated and planned not to pre-tin it.		
Reason for Short Notice :	Force Majeure		
Assessment of Change :	Reliability Test Report/s		
Planned Implementation Date :	May 02, 2022		
Sample Availability Date:	May 02, 2022		
Internal Molex Qualification Date :	May 02, 2022		
Last date to request Samples by Customer :	April 28, 2022		
Traceability Code Markings / Date :	No special marking on the product or packaging		

Before Picture

Before

This notification is to inform that as the Pre-tinning Process has become highly Instable and inefficient to meet conformance, the product has been reevaluated and planned not to be pre-tinned.



1

After Picture

After

The Product after the discontinuation of the Pre-tinning will not have the tinned specification.

Please refer attached impacted part list



2

RELEASED

You may address inquires regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:511885
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 511885** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com

PCN No Part List

511885 [1727040050](#)
511885 [1727040051](#)
511885 [1727040052](#)
511885 [1727040053](#)
511885 [1727040054](#)
511885 [1727040055](#)
511885 [1727040056](#)
511885 [1727040057](#)
511885 [1727040058](#)
511885 [1727040060](#)
511885 [1727040061](#)
511885 [1727040201](#)
511885 [1731090384](#)
511885 [1731090536](#)
511885 [1731090868](#)
511885 [1731091157](#)
511885 [1731091308](#)
511885 [1731091610](#)
511885 [1731091687](#)
511885 [1731092262](#)
511885 [1731100024](#)
511885 [1731100025](#)
511885 [1731100026](#)
511885 [1731100027](#)
511885 [1731100028](#)
511885 [1731100029](#)
511885 [1731100030](#)
511885 [1731100031](#)
511885 [1731100032](#)
511885 [1731100033](#)
511885 [1731100034](#)
511885 [1731100064](#)
511885 [1731100068](#)
511885 [1731100073](#)
511885 [1731100075](#)
511885 [1731100080](#)
511885 [1731100104](#)
511885 [1731100106](#)
511885 [1731100107](#)
511885 [1731100120](#)
511885 [1731100127](#)
511885 [1731100140](#)
511885 [1731100149](#)
511885 [1731100157](#)
511885 [1731100161](#)

511885 [1731100162](#)

511885 [1731100163](#)

511885 [1731100164](#)

511885 [1731100167](#)

511885 [1731100168](#)

511885 [1731100173](#)

511885 [1731100247](#)

511885 [1731100249](#)

511885 [1731100250](#)

511885 [1731100313](#)

511885 [1731100317](#)

511885 [1731100344](#)

511885 [1731100356](#)

511885 [1731130319](#)

511885 [1731140379](#)

511885 [1731140380](#)