

Global Change Notification (GCN)

Product Family	Sealed SFP F/O Modules	10668905
		GCN Number
Series	106501	February 23, 2015
		Date Issued
Reason For Change	Obsolescence	
Change Description	This letter is to notify you that due to low overall demand and on-going difficulty with continuous sub-assembly supply Molex will obsolete various part numbers from series 106501. The impacted part numbers are; 106501-1000, 106501-2000, 106501-3000.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes	
Assessment Of Change (How Product Will Be Qualified & Validated)		
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	February 23, 2015	
Method of Identifying Change	N/A	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts	January 15, 2015	
Last Time Ship Date for Obsolete Parts	January 31, 2015	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com