

Light is OSRAM



15.10.2018

OS-IN-2018-027

Change tray material with improved anti-static value for Osram Ostar Headlamp Pro.

Objective	Introduction of tray material with improved anti-static value for Ostar Headlamp Pro.	
Products affected	LE UW U1A5 11, LE UW U1A4 11	
Background	During Hyundai Motor's audit at our customer SL, the anti static value of the tray for Ostar was found to be out of their requirement.	
Realization	<u>Current status</u> 1x10 ⁴ -1x10 ¹¹ Ω	<u>New status</u> 1x10 ⁴ -1x10 ⁹ Ω
Time Schedule	Introduction calendar week 50, 2018	

Please direct your inquiry to your local Sales office.

OSRAM Opto Semiconductors
GmbH

Head Office:

Leibnizstrasse 4
93055 Regensburg, Germany
Phone +49 941 850 -5
Fax +49 941 850 -1002
www.osram-os.com



Products Affected by Information Notification

Number: OS-IN-2018-017

Name: Change tray material with improved anti-static value for Osram Ostar Headlamp Pro

Release Date: 10/14/2018

Implementation Date: 12/15/2018

<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>
LE UW U1A4 11	Q65111A9965	LE UW U1A4 11-6R7R-EBZB68-T05-HAN	LE UW U1A4 11-6R7R-EBZB68-T05-HAN
	Q65112A0784	LE UW U1A4 11-6R7R-EBXD68FCBB68-T0	LE UW U1A4 11-6R7R-EBXD68FCBB68
	Q65112A2305	LE UW U1A4 11-6R7R-FCBB68-T05-HAN	LE UW U1A4 11-6R7R-FCBB68-HAN
LE UW U1A5 11	Q65112A0093	LE UW U1A5 11-RUSP-EBZB68-T05-HAN	LE UW U1A5 11-RUSP-EBZB68
	Q65112A0095	LE UW U1A5 11-RUSP-EBXD68FCBB68-T0	LE UW U1A5 11-RUSP-EBXD68FCBB68
	Q65112A2304	LE UW U1A5 11-RUSP-FCBB68-T05-HAN	LE UW U1A5 11-RUSP-FCBB68-HAN