

## Global Change Notification (GCN)

Product Family	POE Series	10729131
		GCN Number
Series	Various	November 05, 2015
		Date Issued
Reason For Change	Supplier Change	
Change Description	To improve the delivery Consolidate the sourcing for the solder bar( component part number 172007609), Molex DG is going to add the new sourcing which already using for other existing projects for the solder bar. There is not any impact for the function and assembly process with the parts from new sourcing. The impact part number list as below: 857281001 857281003 857281004 857281008 857281016 857271001 857271003 857271004 857271008 857271016 857321001 857321002 857321003 857321004 857321006 857321008 857321012 857321013 857322001 857322004 857352001 857352004 857277005	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	Internal qualification report,	
Internal Molex Qualification Date (Planned Date Information Available)	September 15, 2015	
Sample Availability Date (Changed Part)	September 15, 2015	
Date of Implementation	November 23, 2015	
Method of Identifying Change	Datecode	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)