

1 Products affected


Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	001	0000002310	6160.0001	Connector	2561 Appliance Inlet C6	n/a
				6160.0080		2561 Appliance Inlet C6	n/a
				6160.0082		2561 Appliance Inlet C6	n/a
				6160.0086		2561 Appliance Inlet C6	n/a
				6160.0088		2561 Appliance Inlet C6	n/a

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

UL upgrade from UL 498 to UL 60320-1.
Marking for UL rating 7A/125V~ added. CSA / UR replaced by cURus.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

6 Impact of change and recommended action

Form	Yes	Change of approval and rating marking.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 2561	

Product Change Notification					2561 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-052-362
zeierjo	31.03.2021	31.03.2021	muehlema	2019985	B	1 of 1	