



Product Change Notification (PCN)

PCN Number	505685	Date Issued	June 27, 2018
Reason for Change	Manufacturing Process Change (Molex)		
Change Type Description	This letter is to inform you that the manufacturing process for the part(s) identified in this notice is changing. No changes will be made to the product as a result of this process change.		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	October 01, 2018		
Sample Availability Date (Changed Part)	October 01, 2018		
Planned Implementation Date	November 24, 2018		
Method of Identifying Change	Product made after planned implementation date can contain the change		

Before Change

Before

Presently we are manufacturing the minifit headers 87427 & 5569 series by **manual** assembly process by using the **loose pins**.



After Change

After

- Manufacture the minifit headers 87427 & 5569 series by **Automated** assembly process.
- Replace current **loose pins** with **bando pins** which is **manufactured in-house**.



- "No impact to fit, form or function"



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505685**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

39291028

39291048

39291068

39291088

39291108

39291128

39291148

39291168

39291208

39291248

874270202

874270242

874270402

874270442

874270602

874270642

874270802

874270842

874271002

874271042

874271242

874271402

874271442

874271602

874271642

874271802

874271842

874272002

874272042

874272242

874272402

874272442

874272448

39-29-1048

39-29-1068

39-29-1088

39-29-1108

39-29-1148

39-29-1168

39-29-1188

39-29-1208

87427-0242

87427-0802

87427-1202

87427-1402

87427-2002

87427-2402

87427-2422