



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000817

DATE: 15-Jan-2016

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX14675EDEMBD#	N/A			Part reactivated from prior notice: M0008601
Reactivation	MAX14832EWL+T	N/A			Part reactivated from prior notice: M000816
Reactivation	MAX9064EUK/V+	N/A			Part reactivated from prior notice: M000793
Reactivation	MAX97003EWP+	N/A			Part reactivated from prior notice: M000816
Reactivation	MAX97003EWP+T	N/A			Part reactivated from prior notice: M000815
Lead-Free Conversion	806-0480-30-TD	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS3112NC1	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1102EUA	MAX1102EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX1480ACPI	MAX1480ACPI+	15-Jan-2016	15-Jan-2016	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX2511EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Lead-Free Conversion	MAX3265EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Lead-Free Conversion	MAX3645ESEEVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Lead-Free Conversion	MAX3676EHJEVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Lead-Free Conversion	MAX3803EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Lead-Free Conversion	MAX3815EVKIT-DVI	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Lead-Free Conversion	MAX414EPD	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8655ETN/GG8	MAX8655ETN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	78P7200-IH	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS1023S-25	DS1023S-25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1050Z-001	DS1050Z-001+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1077Z-100	DS1077Z-100+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1077Z-203	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS1086Z-42M	DS1086Z-42M+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1091LUA-040/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	DS1091LUA-190/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	DS1091LUA-190/V+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	DS1091LUB-016/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	DS1091LUB-019/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	DS1091LUB-025/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	DS1110S-200	DS1110S-200+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1210	DS1210+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1231-20	DS1231-20+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1231-35	DS1231-35+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1231S-20	DS1231S-20+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1232LPN	DS1232LPN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1232SN	DS1232SN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1233-15	DS1233-15+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1233-5	DS1233-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1233A-15	DS1233A-15+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1233D-5	DS1233D-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1233MS-55/T&R	DS1233MS-55+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1254WB2-150	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS12885Q	DS12885Q+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1305	DS1305+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1305E	DS1305E+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1306	DS1306+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1306E	DS1306E+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1312	DS1312+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1312S	DS1312S+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1312S-2	DS1312S-2+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1315EN-33	DS1315EN-33+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1315EN-33/T&R	DS1315EN-33+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1315S-5	DS1315S-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1321S	DS1321S+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1339C-2#	DS1339C-3#	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1339C-3#	DS1339C-2#	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1339U-33	DS1339U-3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1371U	DS1371U+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1374U-33	DS1374U-3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1390U-33/V+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	DS1391U-33	DS1391U-3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1629S	DS1629S+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	DS1629S/T&R	DS1629S+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1631AU	DS1631AU+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1685E-3	DS1685E-3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1685EN-5	DS1685EN-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1687-5	DS1687-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1687-5IND	DS1687-5IND+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1705ESA	DS1705ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1706LEPA	DS1706LEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1706TESA	DS1706TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1721U	DS1721U+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1775R/T&R	DS1775R+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1775R6-U	DS1775R6+U	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1780E	DS1780E+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS17885S-5	DS17885S-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1804Z-010/GH9	DS1804Z-010+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1811-10	DS1811-10+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1811-15	DS1811-15+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1812-15	DS1812-15+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1813-10	DS1813-10+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1813-5/T&R	DS1813-5+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1814AR-5-U	DS1814AR-5-U+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1814CR-5/T&R	DS1814CR-5+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1818-10	DS1818-10+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1819AR-5-U	DS1819AR-5-U+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1819CR-5-U	DS1819CR-5-U+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1831BS	DS1831BS+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1831C	DS1831C+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1831S	DS1831S+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1833-10	DS1833-10+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1833-5	DS1833-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1833Z-10	DS1833Z-10+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1833Z-5	DS1833Z-5+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS18S20Z	DS18S20Z+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS18S20Z/T&R	DS18S20Z+T&R	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS3112NC1	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS32KHZ/DIP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	DS32KHZN/DIP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS32KHZS	DS32KHZS#	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS32KHZSN	DS32KHZSN#	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS3800	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS3900H1EVKIT#	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	DS4830EVKIT#	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	DS8007-KIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	DS8113-KIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	HFRD32EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	ICL7106CPL+3	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	ICL7107CPL+3	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	ICL7109CPL	ICL7109CPL+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7116CPL+3	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	ICL7126CPL+3	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	ICL7136CPL+3	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	ICL7612BCPA	ICL7612BCPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7621BCSA	ICL7621BCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7621DCSA	ICL7621DCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7660CPA	ICL7660CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7660EPA	ICL7660EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7662EPA	ICL7662EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7665ACSA	ICL7665ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICL7665AISA	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	ICL7665ISA	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	ICM7212IPL	ICM7212IPL+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICM7224IQH	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	ICM7225IPL	ICM7225IPL+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	ICM7242IWE	ICM7242IWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	LM4040BEX3-2.5-T	LM4040BEX3-2.5+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	LM4040BEX3-5.0-T	LM4040BEX3-5.0+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	LM4040BIM3-2.1	LM4040BIM3-2.1+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	LM4040DEM3-2.1	LM4040DEM3-2.1+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	LM4041AEM3-1.2	LM4041AEM3-1.2+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	LM4041AIM3-1.2	LM4041AIM3-1.2+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1033BEUP/GH9	MAX1033BEUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1039AEEE	MAX1039AEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX1044CSA	MAX1044CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1044EPA	MAX1044EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1067AEEE	MAX1067AEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1068ACEG	MAX1068ACEG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1108EUB	MAX1108EUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1109CUB	MAX1109CUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX110ACAP	MAX110ACAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1111EEE	MAX1111EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1111EEE-TG068	MAX1111EEE+TG068	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX111BCAP	MAX111BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX111BEAP	MAX111BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1133BCAP	MAX1133BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1142BCAP	MAX1142BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1145BEAP	MAX1145BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1146BCUP	MAX1146BCUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1149BEUP	MAX1149BEUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX115EAX	MAX115EAX+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX117EAI	MAX117EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX11835EWA+	N/A	15-Jan-2016	15-Jan-2016	Part can no longer be manufactured
Discontinuance	MAX1202AEAP	MAX1202AEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1204BEAP	MAX1204BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX120EWG-T	MAX120EWG+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX121EWE	MAX121EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1232CPA	MAX1232CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1232CSA	MAX1232CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1232CSA-T	MAX1232CSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1232CWE	MAX1232CWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1240CESA	MAX1240CESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1241ACSA	MAX1241ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1243AESA-T	MAX1243AESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1245AEAP	MAX1245AEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1261BEEI	MAX1261BEEI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1261BEEI-T	MAX1261BEEI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX126CCAX	MAX126CCAX+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1270AEAI/GH9	MAX1270AEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1270BCAI	MAX1270BCAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX1270BEAI	MAX1270BEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX127ACAI	MAX127ACAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX127AEAI/GH9	MAX127AEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1282BEUE	MAX1282BEUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1283BEUE	MAX1283BEUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX128BCAI	MAX128BCAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX13087EESA	MAX13087EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX13089EASD	MAX13089EASD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX131CPL	MAX131CPL+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX133CQH	MAX133CQH+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX13442EASA	MAX13442EASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1406CPE	MAX1406CPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1408CAI	MAX1408CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX144ACUA	MAX144ACUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX146BCAP	MAX146BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX146BEAP	MAX146BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX146BEAP-T	MAX146BEAP+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX146BEAP/GH9-T	MAX146BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX147BEAP	MAX147BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1480ACPI	MAX1480ACPI+	15-Jan-2016	15-Jan-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1480BCPI	MAX1480BCPI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1480BEPI	MAX1480BEPI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1482ESD	MAX1482ESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1488EESD-T	MAX1488EESD+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1489ECPD	MAX1489ECPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1489EEPD	MAX1489EEPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX148BEAP	MAX1494CCJ+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1490AEPG	MAX1490AEPG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX149BCAP	MAX149BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX15014AATX+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX15015AEVKIT+	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX15015BATX+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX15016AATX+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX15016BATX+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX15017AATX+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX153EAP	MAX153EAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX154BCAG	MAX154BCAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX158AEAI	MAX158AEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX160EPN	MAX160EPN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1617MEE	MAX1617MEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX161CCPI	MAX161CCPI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX161CEWI	MAX161CEWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX162CCNG	MAX162CCNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX163CENG	MAX163CENG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1640EEE	MAX1640EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1649CPA	MAX1649CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1649ESA	MAX1649ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX164CCNG	MAX164CCNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX164CCWG	MAX164CCWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX165BCPN	MAX165BCPN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1681ESA	MAX1681ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1682EUK	MAX1682EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1683EUK	MAX1683EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1684EEE-T	MAX1684EEE+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1685EEE	MAX1685EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1685EEE-T	MAX1685EEE+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX16935SAUE/V+GE	MAX16935SAUE/V+	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX1706EEE	MAX1706EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1725EUK	MAX1725EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX173CNG	MAX173CNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX174BEWI	MAX174BEWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1793EUE18	MAX1793EUE18+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1793EUE25	MAX1793EUE25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1793EUE25-T	MAX1793EUE25+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1796EUA	MAX1796EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1796EUA-T	MAX1796EUA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1820XEBC+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX186ACPP	MAX186ACPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX186ACWP	MAX186ACWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX186AEAP	MAX186AEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX186BCPP	MAX186BCPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX186BEAP	MAX186BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX186BEWP	MAX186BEWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX186CEWP	MAX186CEWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX187ACWE	MAX187ACWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX187AEPA	MAX187AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX187BCPA	MAX187BCPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX187CCPA	MAX187CCPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX188ACWP	MAX188ACWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX190BCWG	MAX190BCWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX191BENG	MAX191BENG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1928EUB25-T	MAX1928EUB25+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX192ACWP	MAX192ACWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX192BEAP	MAX192BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX194BEWE	MAX194BEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1976AEZT120	MAX1976AEZT120+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX197ACAI	MAX197ACAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX197AEAI	MAX197AEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX197BCAI	MAX197BCAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX197BCWI	MAX197BCWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX201EWE	MAX201EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX2027EUP-D	MAX2027EUP+D	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX202ECPE	MAX202ECPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX202EEUE	MAX202EEUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX202ESE	MAX202ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX203CPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203CWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203ECP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203ECWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203ECWP-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203EPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203EWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203EWP-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203EPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203EWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX203EWP-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX204CPE	MAX204CPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX205ECPG	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX206CAG	MAX206CAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX206ECWG	MAX206ECWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX207EEWG	MAX207EEWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208CAG	MAX208CAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208EAG	MAX208EAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208ECAG	MAX208ECAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208ECNG	MAX208ECNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208ECWG	MAX208ECWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208EEAG-T	MAX208EEAG+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX208EEWG	MAX208EEWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX211CWI	MAX211CWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX211CWI-T	MAX211CWI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX211EAI	MAX211EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX211EWI	MAX211EWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX212EWG	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX213CAI	MAX213CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX213ECAI	MAX213ECAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX213ECWI	MAX213ECWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX218CPP	MAX218CPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX218CWP	MAX218CWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX221CAE	MAX221CAE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX221CUE	MAX221CUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX221EEAE	MAX221EEAE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX222CPN	MAX222CPN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX223EAI	MAX223EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX231CPD	MAX231CPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX231EWE	MAX231EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX231EWE-T	MAX231EWE+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX232ECSE	MAX232ECSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX232EWE	MAX232EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX232ESE	MAX232ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX232MWE/PR-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX233ACPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX233ACWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX233AEPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX233AERP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX233AERP-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX233CPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX233EPP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX235CPG	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX235EPG	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX236CNG	MAX236CNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX236EWG	MAX236EWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX238CWG	MAX238CWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX239EWG	MAX239EWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX24001-EVAL-OA	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX24001TL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX24001TL+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX24002TL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX24002TL+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX24003TL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX24003TL+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX2410EEI	MAX2410EEI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX241CAI	MAX241CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX241CWI	MAX241CWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX241EEWI	MAX241EEWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX242CWN-T	MAX242CWN+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX242EWN	MAX242EWN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX242EWN-T	MAX242EWN+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX250EPD	MAX250EPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX2511EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX251CPD	MAX251CPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX252BCHL-W	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX253MSA/PR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX2605EUT	MAX2605EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX2605EUT-T	MAX2605EUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX261BCWG	MAX261BCWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX265BCWI	MAX265BCWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX2680EUT	MAX2680EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX270CPP	MAX270CPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX291ESA	MAX291ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX292ESA	MAX292ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX297EWE	MAX297EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3001EEUP	MAX3001EEUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3006EUP	MAX3006EUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3030ECSE	MAX3030ECSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3031EESE	MAX3031EESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3032EESE/GH9	MAX3032EESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3040EUE	MAX3040EUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3043EUE	MAX3043EUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3045BCUE	MAX3045BCUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3051ESA	MAX3051ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3054ASD	MAX3054ASD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3057ASA	MAX3057ASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3059ASA	MAX3059ASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3061EEKA	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3061EEKA-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3072EASA	MAX3072EASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3072EESA	MAX3072EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3074EESA	MAX3074EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3074EESA-T	MAX3074EESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3078EASA	MAX3078EASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3079EASD	MAX3079EASD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3082EESA	MAX3082EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3088EESA	MAX3088EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3088EESA-T	MAX3088EESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3095CSE	MAX3095CSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3096CEE	MAX3096CEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3130CAI	MAX3130CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3130EAI	MAX3130EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3131EAI	MAX3131EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3158CAI	MAX3158CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3158EAI	MAX3158EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3160EEAP/GH9	MAX3160EEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3170CAI	MAX3170CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3180EUK	MAX3180EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3186CWP	MAX3186CWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3187CAX	MAX3187CAX+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX3205EABL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX3212EAI	MAX3212EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3218CAP	MAX3218CAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3221CUE	MAX3221CUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3222ECUP	MAX3222ECUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3222ECWN	MAX3222ECWN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3222EEUP	MAX3222EEUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3222EEWN	MAX3222EEWN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3222EUP	MAX3222EUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3223CAP	MAX3223CAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3223CPP	MAX3223CPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3223CUP	MAX3223CUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3223ECAP	MAX3223ECAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3223EEAP/GH9-T	MAX3223EEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3224EAP	MAX3224EAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3224ECAP	MAX3224ECAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3224EEAP	MAX3224EEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3225EAP	MAX3225EAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3225ECP	MAX3225ECP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3226ECAE	MAX3226ECAE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3232CUE	MAX3232CUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3232CWE	MAX3232CWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3232ECUE	MAX3232ECUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3232EEWE	MAX3232EEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3232EPE	MAX3232EPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3232EWE	MAX3232EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3233ECWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3233EEWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3233EEWP-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3235ECWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3235EEWP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3237CAI	MAX3237CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3237EAI	MAX3237EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3237EEAI	MAX3237EEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3238ECAI	MAX3238ECAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3238EEAI	MAX3238EEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX3241EAI	MAX3241EAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3241ECWI	MAX3241ECWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3241EEAI	MAX3241EEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3241EEUI	MAX3241EEUI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3241EEWI-T	MAX3241EEWI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3243ECAI-T	MAX3243ECAI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3243EEUI	MAX3243EEUI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3243EUI	MAX3243EUI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3244CWI	MAX3244CWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3245CAI	MAX3245CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3248EEAI	MAX3248EEAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3265EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX3316ECAE	MAX3316ECAE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3316ECUP	MAX3316ECUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3318ECAP	MAX3318ECAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3320LCAP	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3320TCAP	MAX3320TCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3370EXK	MAX3370EXK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3377EEUD	MAX3377EEUD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3380ECUP	MAX3380ECUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3381ECUP	MAX3381ECUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3381EEUP	MAX3381EEUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3387ECUG	MAX3387ECUG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX339MSE/PR3	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3443ECSA-T	MAX3443ECSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3443EEPA	MAX3443EEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3485ECSA	MAX3485ECSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3485EPA	MAX3485EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3486ECSA	MAX3486ECSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3486ESA	MAX3486ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3488ECPA	MAX3488ECPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3490EESA/GH9-T	MAX3490EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3491ECSD	MAX3491ECSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3645ESEEVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX3665EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX3676EHJEVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX3786UTJ+TG069	MAX3786UTJ+	16-Jul-2016	14-Jan-2018	The part was not released
Discontinuance	MAX3803EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX3815EVKIT-DVI	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX3864EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX394MWP/PR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX4014EUK	MAX4014EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4040EUK	MAX4040EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4042EUA	MAX4042EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4043EUB	MAX4043EUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4073FAXK	MAX4073FAXK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4073FAXK-T	MAX4073FAXK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4073HAUT	MAX4073HAUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4076EUK	MAX4076EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX407ESA	MAX407ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4080TAUA	MAX4080TAUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4080TAUA-T	MAX4080TAUA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4080TAUA/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX4092AUA	MAX4092AUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX409ACPA	MAX409ACPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX409ACSA	MAX409ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX409BESA	MAX409BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX409BESA-T	MAX409BESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4122EUK	MAX4122EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4122EUK-T	MAX4122EUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4123EUA	MAX4123EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4124EUK	MAX4124EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4124EUK-T	MAX4124EUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4125ESA	MAX4125ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4125EUA	MAX4125EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4126ESA	MAX4126ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4128ESA	MAX4128ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX412CSA	MAX412CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4130EUK	MAX4130EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4132ESA	MAX4132ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4162ESA	MAX4162ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4162EUK	MAX4162EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX4163ESA	MAX4163ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4163ESA-T	MAX4163ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4163EUA	MAX4163EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4167EPA	MAX4167EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4168ESD	MAX4168ESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4173FESA	MAX4173FESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4194ESA	MAX4194ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4194ESA-T	MAX4194ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4197ESA	MAX4197ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4197ESA-T	MAX4197ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4198EUA/GH9	MAX4198EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4198EUA/GH9-T	MAX4198EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4202ESA	MAX4202ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4203ESA	MAX4203ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4210EEUA	MAX4210EEUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4222EEE/GH9	MAX4222EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4224EUT	MAX4224EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4237EUT	MAX4237EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4237EUT-T	MAX4237EUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4242ESA	MAX4242ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4242EUA	MAX4242EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4246AKA	MAX4246AKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4246AKA-T	MAX4246AKA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4250EUK	MAX4250EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4250EUK-T	MAX4250EUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4251ESA	MAX4251ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4253ESD	MAX4253ESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4253EUB	MAX4253EUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4266EUA	MAX4266EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4282ESA	MAX4282ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4284ESD	MAX4284ESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4291EXK-T	MAX4291EXK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4305ESA	MAX4305ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4323ESA	MAX4323ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4331ESA	MAX4331ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4356ECD+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX4357ECD+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX4357ECD+D	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX4373TESA	MAX4373TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4374TESD	MAX4374TESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4378FAUD	MAX4378FAUD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4395ESD/V+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX4395ESD/V+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX4402AKA	MAX4402AKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4420EPA	MAX4420EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4447ESE	MAX4447ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4461TESA	MAX4461TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4462TESA	MAX4462TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4478ASD	MAX4478ASD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4480AXK	MAX4480AXK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4486AUA	MAX4486AUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4489AUA	MAX4489AUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4491AKA	MAX4491AKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4492ASD	MAX4492ASD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4493AUK	MAX4493AUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4537EEE/GH9	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX454CSD	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX474MSA/PR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX481MSA/PR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX483ECSA	MAX483ECSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX483ESA	MAX483ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX485CSA	MAX485CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX485ECPA	MAX485ECPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX485ECSA-T	MAX485ECSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX487EESA	MAX487EESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX488CPA	MAX488CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX489CSD	MAX489CSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX489ECPD	MAX489ECPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX491ECPD	MAX491ECPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX491EPD	MAX491EPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX492CSA	MAX492CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX500ACPE	MAX500ACPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX500AEWE	MAX500AEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX500BCWE	MAX500BCWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX500BEWE	MAX500BEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX502ACNG	MAX502ACNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX502BEWG	MAX502BEWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505ACAG	MAX505ACAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505ACWG	MAX505ACWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505ACWG-T	MAX505ACWG+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505AEAG	MAX505AEAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505BCWG	MAX505BCWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505BEAG	MAX505BEAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX505BEWG	MAX505BEWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX506AEWP	MAX506AEWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX508AEWP	MAX508AEWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5105EEP	MAX5105EEP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX510AEWE	MAX510AEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX510BCWE	MAX510BCWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX512CPD	MAX512CPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5141EUA	MAX5141EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5142EUB	MAX5142EUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX514AENG	MAX514AENG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX514BCNG	MAX514BCNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX514BCWI	MAX514BCWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5151AEEE	MAX5151AEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5155AEEE	MAX5155AEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX515CSA	MAX515CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5167MCCM+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX5171AEEE	MAX5171AEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5180BEEI	MAX5180BEEI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5180BEEI-T	MAX5180BEEI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5189BEEI	MAX5189BEEI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5190BEEG-T	MAX5190BEEG+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX519BCSE	MAX519BCSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX521BEWG/GH9	MAX521BEWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5222EKA	MAX5222EKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5250ACAP	MAX5250ACAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX5250AEAP	MAX5250AEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5250BCAP	MAX5250BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5253BCAP	MAX5253BCAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5258EEE	MAX5258EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX525AEAP/GH9	MAX525AEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX525BCPP	MAX525BCPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX525BEAP	MAX525BEAP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX526DCNG	MAX526DCNG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX526DEWG	MAX526DEWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX527CCWG	MAX527CCWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX527DMYG	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX528CPP	MAX528CPP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX528EWG	MAX528EWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5291BEUE	MAX5291BEUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5295EUE	MAX5295EUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5302EUA	MAX5302EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX530BEAG	MAX530BEAG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX531ACSD	MAX531ACSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX531BCSD	MAX531BCSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX532ACPE	MAX532ACPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX532ACWE	MAX532ACWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX532AEWE/GH9-T	MAX532AEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX532BEPE	MAX532BEPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX534BCEE	MAX534BCEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5352AEUA	MAX5352AEUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5352BEUA	MAX5352BEUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5353BCUA	MAX5353BCUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX536BCPE	MAX536BCPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX537BEWE	MAX537BEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5385EUT	MAX5385EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5385EUT-T	MAX5385EUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX538BCSA	MAX538BCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX538BESA	MAX538BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX539BESA	MAX539BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX541AESA	MAX541AESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX541BCSA	MAX541BCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX541CESA	MAX541CESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX542ACSD	MAX542ACSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX542AESD	MAX542AESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX542BCSD	MAX542BCSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5430AEKA	MAX5430AEKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5430BEKA	MAX5430BEKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX543BCPA	MAX543BCPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5443ACUA	MAX5443ACUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX544BCSA	MAX544BCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5468EUT	MAX5468EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5471EZT-T	MAX5471EZT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX547BCMH	MAX547BCMH+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5480AEEE	MAX5480AEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5480BEEE	MAX5480BEEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX548AEPA	MAX548AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5492LA07538-T	MAX5492LA07538+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX552AEUB	MAX552AEUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5541CSA	MAX5541CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5590BEUG	MAX5590BEUG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX561CAI	MAX561CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX562CAI	MAX562CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5721AUA	MAX5721AUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5811LEUT	MAX5811LEUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5811NEUT	MAX5811NEUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5822LEUA	MAX5822LEUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5822MEUA	MAX5822MEUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6002EUR	MAX6002EUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6003EUR	MAX6003EUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6003EUR-T	MAX6003EUR+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6006AEUR	MAX6006AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6007AEUR	MAX6007AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6007AEUR-T	MAX6007AEUR+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6012AEUR	MAX6012AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6025AEUR	MAX6025AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6029ESA25	MAX6029ESA25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6029ESA25/GH9-T	MAX6029ESA25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX6029EUK25/GH9-T	MAX6029EUK25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6034AEXR25	MAX6034AEXR25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6034BEXR25	MAX6034BEXR25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6035AAUR50-T	MAX6035AAUR50+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6035BAUR30	MAX6035BAUR30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6037AAUK12-T	MAX6037AAUK12+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6037BAUK30	MAX6037BAUK30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6037CAUK30	MAX6037CAUK30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6045AEUR	MAX6045AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6045BEUR	MAX6045BEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6064AEUR	MAX6064AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6066AEUR/GH9-T	MAX6066AEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6068BEUR	MAX6068BEUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX608EPA	MAX608EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6102EUR	MAX6102EUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6103EUR	MAX6103EUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6120ESA	MAX6120ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6125EUR	MAX6125EUR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6126A50	MAX6126A50+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6126AASA30	MAX6126AASA30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6129AEUK30	MAX6129AEUK30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6129AEUK30-T	MAX6129AEUK30+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6138AEXR21	MAX6138AEXR21+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6138AEXR21-T	MAX6138AEXR21+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6138AEXR30-T	MAX6138AEXR30+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6138AEXR33	MAX6138AEXR33+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6138BEXR12	MAX6138BEXR12+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6138CEXR21	MAX6138CEXR21+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6161BESA	MAX6161BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6162AESA	MAX6162AESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6166BESA	MAX6166BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6175AASA	MAX6175AASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6176BASA	MAX6176BASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6177BASA	MAX6177BASA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX619CSA	MAX619CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX619ESA	MAX619ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX620CWN	MAX620CWN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6225BESA	MAX6225BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6241ACSA	MAX6241ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6250BCSA	MAX6250BCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6301CUA	MAX6301CUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6302ESA	MAX6302ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6303CSA	MAX6303CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6304CUA	MAX6304CUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6304ESA	MAX6304ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX630EPA	MAX630EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6316LUK46BY-T	MAX6316LUK46BY+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6316LUK46CY	MAX6316LUK46CY+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6318LHUK48BX	MAX6318LHUK48BX+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6321HPUK31AY-T	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX6324BUT29	MAX6324BUT29+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6324HUT29	MAX6324HUT29+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6324HUT29-T	MAX6324HUT29+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6326UR25	MAX6326UR25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6326UR31-T	MAX6326UR31+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6326XR26-T	MAX6326XR26+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6326XR29	MAX6326XR29+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6326XR30	MAX6326XR30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX632ACPA	MAX632ACPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX632ACSA	MAX632ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6338BUB	MAX6338BUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6338JUB	MAX6338JUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6338OUB	MAX6338OUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX633ACSA	MAX633ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX633AEPA	MAX633AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX634CPA	MAX634CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX634EPA	MAX634EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX634ESA	MAX634ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6350EPA	MAX8069ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6351LSUT	MAX6351LSUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6355MSUT	MAX6355MSUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6355SVUT	MAX6355SVUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX6355SYUT-T	MAX6355SYUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6358LSUT	MAX6358LSUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6359LTUT	MAX6359LTUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6359LTUT-T	MAX6359LTUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6363PUT29	MAX6363PUT29+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX636ACPA	MAX636ACPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6383XR46D2	MAX6383XR46D2+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6383XR46D2-T	MAX6383XR46D2+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6389XS29D3/GH9T	MAX6389XS29D3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6390XS26D4	MAX6390XS26D4+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX639CSA	MAX639CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX639EPA	MAX639EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX640CPA	MAX640CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX640ESA	MAX640ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6412UK30-T	MAX6412UK30+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6418UK23-T	MAX6418UK23+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6419UK29	MAX6419UK29+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX641AEPA	MAX641AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX641AESA	MAX641AESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6433UK/GH9-T	MAX6433UK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6446UK29L	MAX6446UK29L+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6458UKD0B/GH9-T	MAX6458UKD0B+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6466UR23	MAX6466UR23+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX649CSA+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX649EPA+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX6501UKP075	MAX6501UKP075+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6510CAUT	MAX6510CAUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6510HAUT-T	MAX6510HAUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX651ESA+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX653CSA	MAX653CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6611AUT	MAX6611AUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX662AEPA	MAX662AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX664EPA	MAX664EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6652AUB-T	MAX6652AUB+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6654MEE	MAX6654MEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6654MEE-T	MAX6654MEE+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX6656MEE	MAX6656MEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6657MSA	MAX6657MSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX667CPA	MAX667CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6683AUB	MAX6683AUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6685AU40H	MAX6685AU40H+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6698AEE	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX6698EE99	MAX6698EE99+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX669EUB	MAX669EUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6709MUB	MAX6709MUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6714DUB	MAX6714DUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6736XKRVD3	MAX6736XKRVD3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6736XKSHD3	MAX6736XKSHD3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6736XKSHD3-T	MAX6736XKSHD3+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6737XKTZD3	MAX6737XKTZD3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6737XKTZD3-T	MAX6737XKTZD3+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6744XKTGD3	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX6745XKRD3	MAX6745XKRD3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6745XKRD3-T	MAX6745XKRD3+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6747KA45	MAX6747KA45+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX674ESA	MAX674ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6764UT/GH9-T	MAX6764UT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX680CPA	MAX680CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX680ESA	MAX680ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX680ESA-T	MAX680ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6814XK	MAX6814XK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6817EUT/GH9	MAX6817EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6817EUT/GH9-T	MAX6817EUT+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6819UT-T	MAX6819UT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6823SUK-T	MAX6823SUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6823TUK	MAX6823TUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6831YGUT-T	MAX6831YGUT+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6839XSD3	MAX6839XSD3+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX685EEE	MAX685EEE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6861UK16	MAX6861UK16+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX690ACSA	MAX690ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX690CPA	MAX690CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX690SCSA	MAX690SCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX690TESA	MAX690TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX691AEWE	MAX691AEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX691CWE	MAX691CWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX691CWE-T	MAX691CWE+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX692ACPA	MAX692ACPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6931AUI	MAX6931AUI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX693ACWE	MAX693ACWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX693ACWE-T	MAX693ACWE+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX693CWE	MAX693CWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX693EWE	MAX693EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6957AAX/GH9	MAX6957AAX+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX695CPE	MAX695CPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6980AUE+	N/A	16-Jul-2016	14-Jan-2018	The part was not released
Discontinuance	MAX699EWE	MAX699EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX700CSA	MAX700CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX700ESA	MAX700ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX701CPA	MAX701CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX701CSA	MAX701CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX701ESA	MAX701ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX702CSA	MAX702CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX702ESA	MAX702ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX702ESA-T	MAX702ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX703CSA	MAX703CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX703ESA	MAX703ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX704CSA	MAX704CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX704SESA	MAX704SESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX704TCSA	MAX704TCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX704TESA-T	MAX704TESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX705CUA	MAX705CUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706CSA	MAX706CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706ESA	MAX706ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706REPA	MAX706REPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706SCPA	MAX706SCPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706SCSA	MAX706SCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706SESA	MAX706SESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX706TCSA	MAX706TCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706TCSA-T	MAX706TCSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706TCUA	MAX706TCUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706TEUA	MAX706TEUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX706TEUA-T	MAX706TEUA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX707CSA	MAX707CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX707CSA-T	MAX707CSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX707MSA/PR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX708EPA	MAX708EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX708EUA	MAX708EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX708RCSA	MAX708RCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX708SCSA	MAX708SCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX708SCUA	MAX708SCUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX708TCSA	MAX708TCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX708TESA	MAX708TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX709LCUA	MAX709LCUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX709LESA	MAX709LESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX709MCSA	MAX709MCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX709MESA	MAX709MESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX709RCSA	MAX709RCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX709SCSA	MAX709SCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX710ESE	MAX710ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX711ESE	MAX711ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX732EWE	MAX732EWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX735CSA	MAX735CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX736CPD	MAX736CPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX736CWE	MAX736CWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX738AEPA	MAX738AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX738AEWE	MAX738AEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7403ESA	MAX7403ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7404ESA	MAX7404ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7408EUA	MAX7408EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7414EUA	MAX7414EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7419EUA	MAX7419EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7420EUA	MAX7420EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7425EUA	MAX7425EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX7426CUA	MAX7426CUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7432EUD+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX744ACWE	MAX744ACWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7456EUI+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX7456EUI+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX7456EVKIT+	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX748AEPA	MAX748AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX749CPA	MAX749CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7500MUA	MAX7500MUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7501MSA	MAX7501MSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7501MUA	MAX7501MUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX750ACSA	MAX750ACSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX755CSA	MAX755CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX755CSA-T	MAX755CSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX756CPA	MAX756CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX756EPA	MAX756EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX756ESA	MAX756ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX757CPA	MAX757CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX758AEPA	MAX758AEPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX759CPD	MAX758ACWE	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX7624CSE	MAX7624CSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX7645BCWP	MAX7645BCWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX764CPA	MAX764CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX765CSA	MAX765CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX766CSA	MAX766CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX769EEI	MAX769EEI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX770CPA	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX770CSA	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX772CPA	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX773EPD	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX775ESA-T	MAX775ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX791CSE	MAX791CSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX791ESE	MAX791ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX792SESE	MAX792SESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX793SCSE	MAX793SCSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX793SESE	MAX793SESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX793TCPE-G079	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX795SCSA	MAX795SCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX797CSE	MAX797CSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX797ESE/GH9	MAX797ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX798ESE	MAX798ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX800LCSE	MAX800LCSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX807LCPE	MAX807LCPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX807MEWE	MAX807MEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX807NEUE	MAX807NEUE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX807NEWE	MAX807NEWE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX809HEUR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX809REXR-T	MAX809REXR+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX813LCSA	MAX813LCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX813LESA	MAX813LESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX814KESA	MAX814KESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX814NESA	MAX814NESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX814TESA	MAX814TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX815LESA	MAX815LESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX815NCSA	MAX815NCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX815TCSA	MAX815TCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX815TESA	MAX815TESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX816CSA	MAX816CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX817LESA	MAX817LESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX817MCSA	MAX817MCSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX818MCUA	MAX818MCUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX819LCUA	MAX819LCUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8211CSA	MAX8211CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8213BCSE	MAX8213BCSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8214ACSE	MAX8214ACSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8215CSD	MAX8215CSD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8216CPD	MAX8216CPD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX823LEUK	MAX823LEUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX823LEUK-T	MAX823LEUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX824SEUK-T	MAX824SEUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX825LEUK	MAX825LEUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX847EEI	MAX847EEI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX848ESE	MAX848ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX849ESE	MAX849ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8510EXK25	MAX8510EXK25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8510EXK30	MAX8510EXK30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX860ESA	MAX860ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8655ETN/GG8	MAX8655ETN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8676EWJ+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX8698CEMO+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX8698CEMO+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX873BESA	MAX873BESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX875AESA	MAX875AESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX881EVKIT	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX883CSA	MAX883CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8860EUA25	MAX8860EUA25+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8863REUK	MAX8863REUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8863TEUK/GH9	MAX8863TEUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8863TEUK/GH9-T	MAX8863TEUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8868EUK32	MAX8868EUK32+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8873TEUK	MAX8873TEUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8873TEUK-T	MAX8873TEUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8877EUK30	MAX8877EUK30+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8877EUK36	MAX8877EUK36+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8877EUK50	MAX8877EUK50+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8878EUK28	MAX8878EUK28+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8878EUK28-T	MAX8878EUK28+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8878EUK33	MAX8878EUK33+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8878EUK33-T	MAX8878EUK33+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8957BEWI+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9000EUA	MAX9000EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9000EUA-T	MAX9000EUA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9001EUB	MAX9001EUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9013EUA	MAX9013EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9017BEKA-T	MAX9017BEKA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX901ACSE	MAX901ACSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX901BCPE	MAX901BCPE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9034AUD	MAX9034AUD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX903CSA	MAX903CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9053AEUB	MAX9053AEUB+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9075EUK	MAX9075EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9075EUK-T	MAX9075EUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9075EXK	MAX9075EXK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9077EKA-T	MAX9077EKA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9077EKA/GH9-T	MAX9077EKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX907CSA	MAX907CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX907EPA	MAX907EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9111EKA/GH9	MAX9111EKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9111EKA/GH9-T	MAX9111EKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX912CSE	MAX912CSE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX912ESE/GH9	MAX912ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX913CPA	MAX913CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9140EUK-T	MAX9140EUK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX918ESA	MAX918ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX919ESA	MAX919ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9203EKA	MAX9203EKA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX920ESA	MAX920ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX920EUK	MAX920EUK+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX921CSA	MAX921CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX921CSA-T	MAX921CSA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX922CPA	MAX922CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX922CSA	MAX922CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX931EPA	MAX931EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9320ESA	MAX9320ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9320ESA-T	MAX9320ESA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9325EQI-T	MAX9325EQI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX932CSA	MAX932CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX941CSA	MAX941CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX942CPA	MAX942CPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX942EPA	MAX942EPA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9509ATA+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9509ATA+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9598CTL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9601EUP	MAX9601EUP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MAX9602EUG	MAX9602EUG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX964ESE	MAX964ESE+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9667ETP+	N/A	15-Sep-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9667ETP+T	N/A	15-Sep-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9667EVKIT+	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX9670CTL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9670CTL+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9670EVKIT+	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX9675ECQ+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9675ECQ+D	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9675ECQ+T	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9675EVKIT+	N/A	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX967ESA	MAX967ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX967EUA	MAX967EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX968ESA	MAX968ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9713EVKIT	MAX9713EVKIT+	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAX971CSA	MAX971CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX976ESA	MAX976ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9775EBX+G45	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX9775EBX+TG45	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MAX981CSA	MAX981CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX985ESA	MAX985ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX986ESA	MAX986ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX988EXK-T	MAX988EXK+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX989EKA-T	MAX989EKA+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX992EUA	MAX992EUA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX993ESD	MAX993ESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX995ESD	MAX995ESD+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAXQ1740-KIT#	MAXQ1741-KIT#	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	MAXQ7670ATL+	N/A	16-Jul-2016	14-Jan-2018	Part can no longer be manufactured
Discontinuance	MX574AJEWI	MX574AJEWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX574AJP	MX574AJP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX574AKEWI	MX574AKEWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX574AKEWI-T	MX574AKEWI+T	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX574AKEWI/GH9	MX574AKEWI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX574AKN	MX574AKN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Feb-2016

Discontinuance	MX7226KCWP	MX7226KCWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7228KN	MX7228KN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7228KP	MX7228KP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7528KEQP	MX7528KEQP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7534JN	MX7534JN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7537JN	MX7537JN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7537LCWG	MX7537LCWG+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7538JN	MX7538JN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7538KN	MX7538KN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7542JN	MX7542JN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7543JN	MX7543JN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7545GLCWP	MX7545GLCWP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7545KP	MX7545KP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7548JP	MX7548JP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7575KEWN	MX7575KEWN+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7828KP	MX7828KP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7837JR	MX7837JR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MX7847BR	MX7847BR+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MXD1210CSA	MXD1210CSA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MXD1210ESA	MXD1210ESA+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MXL1543BCAI	MXL1543BCAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MXL1543CAI	MXL1543CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MXL1544CAI	MXL1544CAI+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	NBRU66DEVBRD#	MAX1493XSEVKIT#	15-Jan-2016	15-Jan-2016	EVKIT is No Longer Supported
Discontinuance	PHY1066-01BS-BR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	PHY1066-01BS-C56	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	PHY1068-01BL-RR	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	PHY1096-01DS-WR	N/A	15-Jan-2016	15-Jan-2016	Part is leaded. Request information on lead-free version
Discontinuance	REF02CSA-G107	REF02CSA+G107	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	REF02HP	REF02HP+	16-Jul-2016	14-Jan-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	STM1E-SFP22	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	STM1E-SFP23	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	STM1E-SFP26	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	STM1E-SFP35	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version
Discontinuance	STM1E-SFP96	N/A	16-Jul-2016	14-Jan-2018	Part is leaded. Request information on lead-free version