

PRODUCT CHANGE NOTIFICATION

PCN#: RACKS CABLE MGMT 20190207-1

ISSUE DATE: 20190218

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

These Non-Standard products will be discontinued without replacement.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	5	18

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
CMVR19/N	
PRD672A/N	
PRV672A/N	
R2P6WFWWH/N	
RVCMIDFK/N	
NKUFB24/N	
PZC18SWH/N	
PZC22SWH/N	
PZC26SWH/N	
PZC33SWH/N	
PZCL-X/N	
PZWKM8132/N	
PZWC35I/N	
PZWRKB/N	
ER4P36ACEPKWH/N	
CMLT19WH1/N	
CMR19X108NU/N	
CMR19X108NUWH/N	
CMR19X84AL/N	
CMUT19WH1/N	
CRTW23/N	
CRTWWH1/N	
ER4P23108WH/N	
ER4P23108WWH/N	
ER4P2396WH/N	
ER4P2396WWH/N	
ER4P23WH/N	
ER4P23WWH/N	
ER4P29108WH/N	
ER4P2996CNWH/N	
ER4P2996WH/N	
ER4P2996WWH/N	
ER4P29CNWH/N	
ER4P29WWH/N	
ER4P36108ACEPWH/N	
ER4P36108/N	
ER4P36108WWH/N	
ER4P36KITWH/N	
ER4P36WH/N	
ER4P36WWH/N	
ER4P3996CNWH/N	
ER4P39CNWH/N	
ER4PACTPWH/N	
ER4PACTSPBWH/N	
ER4PACTSPWH/N	
ER4PRK/N	

ER4PRKWH/N	
ER4PRKW/N	
ER4PRKWWH/N	
HPPDU1/N	
GOGLETHERM	
R19X1084P7NUWH/N	
R19X844P30/N	
R19X964P30/N	
R19X964P30WH/N	
R2P108WH/N	
R2P108WWH/N	
R2P12S96CNWH/N	
R2P12S96WH/N	
R2P12SCNWH/N	
R2P12SM6WH/N	
R2P12SWH/N	
R2P6S108CNWH/N	
R2P6S96M6WH/N	
R2P6SM6WH/N	
R2PS108CNWH/N	
R2PS108/N	
R2PS108WH/N	
R2PS108WWH/N	
R2PS34WH/N	
R2PS36/N	
R2PS40/N	
R2PS79/N	
R2PS96M6WH/N	
R2PSM6WH/N	
R2PWH1/N	
R4PERT/N	
RFC4U/N	
SRM19FM2AWH/N	
SRM19FM2BWH/N	
SRM19MK2WH/N	
SRM26CM4WH/N	