



Product Change Notification - GBNG-20VJLK817

Date:

05 Apr 2019

Product Category:**Notification subject:**

CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Notification text:**PCN Status:**

Final notification

PCN Type:

Part number convention change

Microchip Parts Affected:

Please open the attachments found in the attachments field below labeled as PCN_#_Affected_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

Description of Change:

Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Please make the necessary revisions to ensure flawless order/entry and receipt of your products.

Pre and Post Change Information:

Please see the attached affected catalog part number (CPN) list to identify the products affected and changes between the current and new catalog part numbers.

Note: As part of the transition to Microchip system, there is a character limitation for these selected Microsemi (LCLD, VPT, TIM and WIFI) part numbers. As a result, the naming convention needs to be changed. To ensure accuracy after the implementation date please query your local sales office with questions if the part number you order is the same as the catalog part number identified in the first column of the attached files.

Impacts to Data Sheet:

None

Change Impact:

None

Reason for Change:

To improve productivity as part of the integration of Microsemi and Microchip.

Change Implementation Status:

In Progress

Implementation Date:

May 1, 2019

Time Table Summary:

	March 2019					->	May 2019				
Workweek	09	10	11	12	13		18	19	20	21	22
Final PCN Issue Date					X						
Anticipated Implementation Date							X				

Method to Identify Change:

Catalog Part Number (CPN)

Qualification Report:



Not applicable

Contact Microchip:

You may contact your local [Microchip Sales and Distribution](#). Contact information is also provided on the attached Frequently Asked Questions (FAQ).

If applicable, please also copy your local Microchip field sales and/or field quality representative.

Revision History:

March 27, 2019: Issued final notification.

April 05, 2019: Re-issued final notification. Revised the notification subject and description of change and updated the affected CPN list to include additional part numbers.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

[Frequently Asked Questions Microsemi May 2019.pdf](#)

[PCN_GBNG-20VJLK817 Affected CPN.pdf](#)

[PCN_GBNG-20VJLK817 Affected CPN.xlsx](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
CLQ214029/KW/BP2N	CLQ214029/KW/BP2N	CLQ214029/KW/BP2N
CR314+	CR314+	CR3142
DS3100GN+	DS3100GN+	DS3100GN2
DS3100SWG+	DS3100SWG+	DS3100SWG2
DS3102GN+	DS3102GN+	DS3102GN2
DS3104GN+	DS3104GN+	DS3104GN2
DS3105LN+	DS3105LN+	DS3105LN2
DS3106LN+	DS3106LN+	DS3106LN2
DS31400GN+	DS31400GN+	DS31400GN2
DS31400SWG+	DS31400SWG+	DS31400SWG2
DS31404GN+	DS31404GN+	DS31404GN2
DS31406GN+	DS31406GN+	DS31406GN2
DS31407GN+	DS31407GN+	DS31407GN2
DS31408GN+	DS31408GN+	DS31408GN2
DS31408SWG+	DS31408SWG+	DS31408SWG2
DS31415GN+	DS31415GN+	DS31415GN2
GSQ20014/PR/NA1C	GSQ20014/PR/NA1C	GSQ20014/PR/NA1C
LE57D111BTC.JC	LE57D111BTC	LE57D111BTC
LE57D111BTCT.JC	LE57D111BTCT	LE57D111BTCT
LE57D121BTC.JC	LE57D121BTC	LE57D121BTC
LE57D121BTCT.JC	LE57D121BTCT	LE57D121BTCT
LE57D122BTC.JC	LE57D122BTC	LE57D122BTC
LE57D122BTCT.JC	LE57D122BTCT	LE57D122BTCT
LE58QL021BVC.JC	LE58QL021BVC	LE58QL021BVC
LE58QL021BVCT.JC	LE58QL021BVCT	LE58QL021BVCT
LE58QL021FJC.JC	LE58QL021FJC	LE58QL021FJC
LE58QL021FJCT.JC	LE58QL021FJCT	LE58QL021FJCT
LE58QL022BVC.JC	LE58QL022BVC	LE58QL022BVC
LE58QL022BVCT.JC	LE58QL022BVCT	LE58QL022BVCT
LE58QL02FJC.JC	LE58QL02FJC	LE58QL02FJC
LE58QL02FJCT.JC	LE58QL02FJCT	LE58QL02FJCT
LE58QL031DJC.JC	LE58QL031DJC	LE58QL031DJC
LE58QL031DJCT.JC	LE58QL031DJCT	LE58QL031DJCT
LE58QL061BVC.JC	LE58QL061BVC	LE58QL061BVC
LE58QL061BVCT.JC	LE58QL061BVCT	LE58QL061BVCT
LE58QL063HVC.JC	LE58QL063HVC	LE58QL063HVC
LE58QL063HVCT.JC	LE58QL063HVCT	LE58QL063HVCT
LE75183CDSCT.JA	LE75183CDSCT	LE75183CDSCT
LE75282BBVC.JA	LE75282BBVC	LE75282BBVC
LE77D112BTC.JC	LE77D112BTC	LE77D112BTC
LE78D110BVC.CA	LE78D110BVC	LE78D110BVC
LE79112AKVC.CA	LE79112AKVC	LE79112AKVC

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
LE79112AKVCT.CA	LE79112AKVCT	LE79112AKVCT
LE79114KVC.MA	LE79114KVC	LE79114KVC
LE79124KVC.MD	LE79124KVC	LE79124KVC
LE79124KVCT.MD	LE79124KVCT	LE79124KVCT
LE79128KVC.ME	LE79128KVC	LE79128KVC
LE79128KVCT.ME	LE79128KVCT	LE79128KVCT
LE7920-1DJCT.JC	LE7920-1DJCT	LE7920-1DJCT
LE792288DGC.JB	LE792288DGC	LE792288DGC
LE79232BTC.JB	LE79232BTC	LE79232BTC
LE79234KVC.MD	LE79234KVC	LE79234KVC
LE792388TVC.MF	LE792388TVC	LE792388TVC
LE792388TVCT.MF	LE792388TVCT	LE792388TVCT
LE792388VQC.MF	LE792388VQC	LE792388VQC
LE792388VQCT.MF	LE792388VQCT	LE792388VQCT
LE79252BTC.JC	LE79252BTC	LE79252BTC
LE79252BTCT.JC	LE79252BTCT	LE79252BTCT
LE79271AMQC.JB	LE79271AMQC	LE79271AMQC
LE79271AMQCT.JB	LE79271AMQCT	LE79271AMQCT
LE79271MQC.JB	LE79271MQC	LE79271MQC
LE79271MQCT.JB	LE79271MQCT	LE79271MQCT
LE79272PQC.JA	LE79272PQC	LE79272PQC
LE79272PQCT.JA	LE79272PQCT	LE79272PQCT
LE7942BDJCT.JC	LE7942BDJCT	LE7942BDJCT
LE79489DJCT.JC	LE79489DJCT	LE79489DJCT
LE79555-2BVC.JC	LE79555-2BVC	LE79555-2BVC
LE79Q2281DVC.JB	LE79Q2281DVC	LE79Q2281DVC
LE79Q2281DVCT.JB	LE79Q2281DVCT	LE79Q2281DVCT
LE79Q2284MVC.JB	LE79Q2284MVC	LE79Q2284MVC
LE79Q2284MVCT.JB	LE79Q2284MVCT	LE79Q2284MVCT
LE79R70-1DJC.JC	LE79R70-1DJC	LE79R70-1DJC
LE79R70-1DJCT.JC	LE79R70-1DJCT	LE79R70-1DJCT
LE79R70-1FQC.JC	LE79R70-1FQC	LE79R70-1FQC
LE79R70DJC.JC	LE79R70DJC	LE79R70DJC
LE79R70DJCT.JC	LE79R70DJCT	LE79R70DJCT
LE79R79-1DJC.JC	LE79R79-1DJC	LE79R79-1DJC
LE79R79-1DJCT.JC	LE79R79-1DJCT	LE79R79-1DJCT
LE79R79-1FQC.JC	LE79R79-1FQC	LE79R79-1FQC
LE79R79-2DJC.JC	LE79R79-2DJC	LE79R79-2DJC
LE79R79-2DJCT.JC	LE79R79-2DJCT	LE79R79-2DJCT
LE79R79-3DJC.JC	LE79R79-3DJC	LE79R79-3DJC
LE79R79-3DJCT.JC	LE79R79-3DJCT	LE79R79-3DJCT
LE8577LFJCT.JA	LE8577LFJCT	LE8577LFJCT

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
LE87100NQC.JA	LE87100NQC	LE87100NQC
LE87100NQCT.JA	LE87100NQCT	LE87100NQCT
LE87251NQC.JA	LE87251NQC	LE87251NQC
LE87251NQCT.JA	LE87251NQCT	LE87251NQCT
LE87270NQC.JA	LE87270NQC	LE87270NQC
LE87270NQC.JB	LE87270NQC	LE87270NQC
LE87270NQCT.JA	LE87270NQCT	LE87270NQCT
LE87270NQCT.JB	LE87270NQCT	LE87270NQCT
LE87280SQC.JAAAX	LE87280SQC	LE87280SQC
LE87281NQC.JB	LE87281NQC	LE87281NQC
LE87281NQCT.JB	LE87281NQCT	LE87281NQCT
LE87282MQC.JB	LE87282MQC	LE87282MQC
LE87282MQCT.JB	LE87282MQCT	LE87282MQCT
LE87285NQC.JA	LE87285NQC	LE87285NQC
LE87285NQCT.JA	LE87285NQCT	LE87285NQCT
LE87286NQC.JMABDX	LE87286NQC	LE87286NQC
LE87290YQC.JA	LE87290YQC	LE87290YQC
LE87290YQCT.JA	LE87290YQCT	LE87290YQCT
LE87401NQC.JB	LE87401NQC	LE87401NQC
LE87401NQCT.JB	LE87401NQCT	LE87401NQCT
LE87402MQC.JA	LE87402MQC	LE87402MQC
LE87402MQCT.JA	LE87402MQCT	LE87402MQCT
LE87411NQC.JA	LE87411NQC	LE87411NQC
LE87411NQCT.JA	LE87411NQCT	LE87411NQCT
LE87501NQC.JA	LE87501NQC	LE87501NQC
LE87501NQCT.JA	LE87501NQCT	LE87501NQCT
LE87502MQC.JA	LE87502MQC	LE87502MQC
LE87502MQCT.JA	LE87502MQCT	LE87502MQCT
LE87511NQC.JA	LE87511NQC	LE87511NQC
LE87511NQCT.JA	LE87511NQCT	LE87511NQCT
LE87536NQC.JA	LE87536NQC	LE87536NQC
LE87536NQCT.JA	LE87536NQCT	LE87536NQCT
LE87557NQC.JA	LE87557NQC	LE87557NQC
LE87557NQCT.JA	LE87557NQCT	LE87557NQCT
LE87611NQC.JA	LE87611NQC	LE87611NQC
LE87611NQCT.JA	LE87611NQCT	LE87611NQCT
LE87612MQC.JA	LE87612MQC	LE87612MQC
LE87612MQCT.JA	LE87612MQCT	LE87612MQCT
LE87614MQC.JA	LE87614MQC	LE87614MQC
LE87614MQCT.JA	LE87614MQCT	LE87614MQCT
LE88010BQC.CC	LE88010BQC	LE88010BQC
LE88010BQCT.CC	LE88010BQCT	LE88010BQCT

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
LE88101DVC.A	LE88101DVC	LE88101DVC
LE88102KQC.JA	LE88102KQC	LE88102KQC
LE88111BLC.VC	LE88111BLC	LE88111BLC
LE88131BLC.VC	LE88131BLC	LE88131BLC
LE88131BLCT.VC	LE88131BLCT	LE88131BLCT
LE88221DLC.VC	LE88221DLC	LE88221DLC
LE88221DLCT.VC	LE88221DLCT	LE88221DLCT
LE88231DLC.VC	LE88231DLC	LE88231DLC
LE88231DLCT.VC	LE88231DLCT	LE88231DLCT
LE88241DLC.E	LE88241DLC	LE88241DLC
LE88241DLC.VC	LE88241DLC	LE88241DLC
LE88241DLCT.VC	LE88241DLCT	LE88241DLCT
LE88262TQC.A	LE88262TQC	LE88262TQC
LE88262TQCT.A	LE88262TQCT	LE88262TQCT
LE88266DLC.A	LE88266DLC	LE88266DLC
LE88266DLCT.A	LE88266DLCT	LE88266DLCT
LE88266TQC.A	LE88266TQC	LE88266TQC
LE88266TQCT.A	LE88266TQCT	LE88266TQCT
LE88276DLC.A	LE88276DLC	LE88276DLC
LE88276DLCT.A	LE88276DLCT	LE88276DLCT
LE88286DLC.A	LE88286DLC	LE88286DLC
LE88286DLCT.A	LE88286DLCT	LE88286DLCT
LE88286TQC.A	LE88286TQC	LE88286TQC
LE88286TQCT.A	LE88286TQCT	LE88286TQCT
LE88506DVC.A	LE88506DVC	LE88506DVC
LE88506DVCT.A	LE88506DVCT	LE88506DVCT
LE88536PQC.JA	LE88536PQC	LE88536PQC
LE88830KQC.JA	LE88830KQC	LE88830KQC
LE88830KQCT.JA	LE88830KQCT	LE88830KQCT
LE89010QVC.A	LE89010QVC	LE89010QVC
LE89010QVCT.A	LE89010QVCT	LE89010QVCT
LE89116QVC.A	LE89116QVC	LE89116QVC
LE89116QVCT.A	LE89116QVCT	LE89116QVCT
LE89156PQC.A	LE89156PQC	LE89156PQC
LE89156PQCT.A	LE89156PQCT	LE89156PQCT
LE89316QVC.A	LE89316QVC	LE89316QVC
LE89316QVCT.A	LE89316QVCT	LE89316QVCT
LE89810BSC.JA	LE89810BSC	LE89810BSC
LE89810BSCT.JA	LE89810BSCT	LE89810BSCT
LE89900AMC.PA	LE89900AMC	LE89900AMC
LE89900AMCT.PA	LE89900AMCT	LE89900AMCT
LE9500ABJCT.JF	LE9500ABJCT	LE9500ABJCT

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
LE9500DBJCT.JF	LE9500DBJCT	LE9500DBJCT
LE9530CETC.JB	LE9530CETC	LE9530CETC
LE9530CETCT.JB	LE9530CETCT	LE9530CETCT
LE9530CPQC.JB	LE9530CPQC	LE9530CPQC
LE9530CPQCT.JB	LE9530CPQCT	LE9530CPQCT
LE9530DETC.JB	LE9530DETC	LE9530DETC
LE9530DETC.JB	LE9530DETC	LE9530DETC
LE9530DPQC.JB	LE9530DPQC	LE9530DPQC
LE9530DPQCT.JB	LE9530DPQCT	LE9530DPQCT
LE9535DETCT.JB	LE9535DETCT	LE9535DETCT
LE9540CUQC.JA	LE9540CUQC	LE9540CUQC
LE9540CUQC.JB	LE9540CUQC	LE9540CUQC
LE9540CUQCT.JA	LE9540CUQCT	LE9540CUQCT
LE9540CUQCT.JB	LE9540CUQCT	LE9540CUQCT
LE9540DUQC.JA	LE9540DUQC	LE9540DUQC
LE9540DUQC.JB	LE9540DUQC	LE9540DUQC
LE9540DUQCT.JA	LE9540DUQCT	LE9540DUQCT
LE9540DUQCT.JB	LE9540DUQCT	LE9540DUQCT
LE9541CUQC.JA	LE9541CUQC	LE9541CUQC
LE9541CUQC.JB	LE9541CUQC	LE9541CUQC
LE9541CUQCT.JA	LE9541CUQCT	LE9541CUQCT
LE9541CUQCT.JB	LE9541CUQCT	LE9541CUQCT
LE9541DUQC.JA	LE9541DUQC	LE9541DUQC
LE9541DUQC.JB	LE9541DUQC	LE9541DUQC
LE9541DUQCT.JA	LE9541DUQCT	LE9541DUQCT
LE9541DUQCT.JB	LE9541DUQCT	LE9541DUQCT
LE9551CMQC.JB	LE9551CMQC	LE9551CMQC
LE9551CMQCT.JB	LE9551CMQCT	LE9551CMQCT
LE9551DMQC.JB	LE9551DMQC	LE9551DMQC
LE9551DMQCT.JB	LE9551DMQCT	LE9551DMQCT
LE9621AQC.AC	LE9621AQC	LE9621AQC
LE9643AQC.A103X	LE9643AQC	LE9643AQC
LE9622RQC.AB	LE9622RQC	LE9622RQC
LE9662WQC.AC	LE9662WQC	LE9662WQC
LE9632RQC.AB	LE9632RQC	LE9632RQC
LE9672WQC.AC	LE9672WQC	LE9672WQC
LE9641PQC.AD	LE9641PQC	LE9641PQC
LE9641PQCT.AD	LE9641PQCT	LE9641PQCT
LE9642PQC.AD	LE9642PQC	LE9642PQC
LE9642PQCT.AD	LE9642PQCT	LE9642PQCT
LE9643AQC.AC	LE9643AQC	LE9643AQC
LE9621AQCT.AC	LE9621AQCT	LE9621AQCT

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
LE9643AQCT.AC	LE9643AQCT	LE9643AQCT
LE9651PQC.AD	LE9651PQC	LE9651PQC
LE9651PQCT.AD	LE9651PQCT	LE9651PQCT
LE9652PQC.AD	LE9652PQC	LE9652PQC
ZL88107LDG1.AD	ZL88107LDG1	ZL88107LDG1
LE9653AQC.AB	LE9653AQC	LE9653AQC
LE9653AQCT.AB	LE9653AQCT	LE9653AQCT
LE9661WQC.AB	LE9661WQC	LE9661WQC
LE9661WQCT.AB	LE9661WQCT	LE9661WQCT
ZL88601LDG1.AE	ZL88601LDG1	ZL88601LDG1
ZL88602LDG1.AE	ZL88602LDG1	ZL88602LDG1
ZL88103LDG1.AE	ZL88103LDG1	ZL88103LDG1
ZL88105LDG1.AC	ZL88105LDG1	ZL88105LDG1
MAX24188ETK+	MAX24188ETK+	MAX24188ETK2
MAX24188ETK+T	MAX24188ETK+T	MAX24188ETK2T
MAX24205EXG+	MAX24205EXG+	MAX24205EXG2
MAX24210EXG+	MAX24210EXG+	MAX24210EXG2
MAX24287ETK+	MAX24287ETK+	MAX24287ETK2
MAX24287ETK+T	MAX24287ETK+T	MAX24287ETK2T
MAX24288ETK+	MAX24288ETK+	MAX24288ETK2
MAX24288ETK+T	MAX24288ETK+T	MAX24288ETK2T
MAX24305EXG+	MAX24305EXG+	MAX24305EXG2
MAX24310EXG+	MAX24310EXG+	MAX24310EXG2
MAX24405EXG+	MAX24405EXG+	MAX24405EXG2
MAX24410EXG+	MAX24410EXG+	MAX24410EXG2
MAX24505EXG+	MAX24505EXG+	MAX24505EXG2
MAX24510EXG+	MAX24510EXG+	MAX24510EXG2
MAX24510EXG+Q00P	MAX24510EXG+Q00P	MAX24510EXG2Q00P
MAX24510EXG+Q00Q	MAX24510EXG+Q00Q	MAX24510EXG2Q00Q
MAX24605EXG+.SB	MAX24605EXG+	MAX24605EXG2
MAX24610EXG+.SB	MAX24610EXG+	MAX24610EXG2
MAX24705EXG+.UB	MAX24705EXG+	MAX24705EXG2
MAX24710EXG+.UB	MAX24710EXG+	MAX24710EXG2
MAX3612ETM+	MAX3612ETM+	MAX3612ETM2
MAX3612ETM+T	MAX3612ETM+T	MAX3612ETM2T
MAX3624AETJ+	MAX3624AETJ+	MAX3624AETJ2
MAX3624AETJ+T	MAX3624AETJ+T	MAX3624AETJ2T
MAX3624UTJ+	MAX3624UTJ+	MAX3624UTJ2
MAX3624UTJ+T	MAX3624UTJ+T	MAX3624UTJ2T
MAX3625ACUG+	MAX3625ACUG+	MAX3625ACUG2
MAX3625ACUG+T	MAX3625ACUG+T	MAX3625ACUG2T
MAX3637ETM+	MAX3637ETM+	MAX3637ETM2

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
MAX3637ETM+T	MAX3637ETM+T	MAX3637ETM2T
MAX3638ETM+	MAX3638ETM+	MAX3638ETM2
MAX3638ETM+T	MAX3638ETM+T	MAX3638ETM2T
MAX3639ETM+	MAX3639ETM+	MAX3639ETM2
MAX3639ETM+T	MAX3639ETM+T	MAX3639ETM2T
MAX3670ETJ+	MAX3670ETJ+	MAX3670ETJ2
MAX3670ETJ+T	MAX3670ETJ+T	MAX3670ETJ2T
MAX3671ETN+	MAX3671ETN+	MAX3671ETN2
MAX3671ETN+T	MAX3671ETN+T	MAX3671ETN2T
MAX3674ECM+	MAX3674ECM+	MAX3674ECM2
MAX3674ECM+T	MAX3674ECM+T	MAX3674ECM2T
MAX3677CTJ+	MAX3677CTJ+	MAX3677CTJ2
MAX3677CTJ+T	MAX3677CTJ+T	MAX3677CTJ2T
MAX3678UTN+	MAX3678UTN+	MAX3678UTN2
MAX3678UTN+T	MAX3678UTN+T	MAX3678UTN2T
MAX3679AETJ+	MAX3679AETJ+	MAX3679AETJ2
MAX3679AETJ+T	MAX3679AETJ+T	MAX3679AETJ2T
MAX3697AETJ+	MAX3697AETJ+	MAX3697AETJ2
MAX3697AETJ+T	MAX3697AETJ+T	MAX3697AETJ2T
MAX3697CTJ+	MAX3697CTJ+	MAX3697CTJ2
MAX3697CTJ+T	MAX3697CTJ+T	MAX3697CTJ2T
MAX3698CTJ+	MAX3698CTJ+	MAX3698CTJ2
MAX3698CTJ+T	MAX3698CTJ+T	MAX3698CTJ2T
MAX9451EHJ+	MAX9451EHJ+	MAX9451EHJ2
MAX9451EHJ+T	MAX9451EHJ+T	MAX9451EHJ2T
MAX9452EHJ+	MAX9452EHJ+	MAX9452EHJ2
MAX9452EHJ+T	MAX9452EHJ+T	MAX9452EHJ2T
ZL30150GGG2.WH	ZL30150GGG2	ZL30150GGG2
ZL30151LDF1.UB	ZL30151LDF1	ZL30151LDF1
ZL30151LDG1.UB	ZL30151LDG1	ZL30151LDG1
ZL30151LDG1QQ01C	ZL30151LDG1QQ01C	ZL30151LDG1QQ01C
ZL30152GGG2.WH	ZL30152GGG2	ZL30152GGG2
ZL30153GGG2.WH	ZL30153GGG2	ZL30153GGG2
ZL30154GGG2.WH	ZL30154GGG2	ZL30154GGG2
ZL30155GGG2.WH	ZL30155GGG2	ZL30155GGG2
ZL30156GGG2.WH	ZL30156GGG2	ZL30156GGG2
ZL30157GGG2.WH	ZL30157GGG2	ZL30157GGG2
ZL30158GGG2.WH	ZL30158GGG2	ZL30158GGG2
ZL30159GGG2.WH	ZL30159GGG2	ZL30159GGG2
ZL30160GGG2.WH	ZL30160GGG2	ZL30160GGG2
ZL30161GDG2.WE	ZL30161GDG2	ZL30161GDG2
ZL30162GDG2.WE	ZL30162GDG2	ZL30162GDG2

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL30163GDG2.WE	ZL30163GDG2	ZL30163GDG2
ZL30163GDG2Q04X.WEAX	ZL30163GDG2Q04X	ZL30163GDG2Q04X
ZL30164GDG2.WE	ZL30164GDG2	ZL30164GDG2
ZL30165GDG2.WE	ZL30165GDG2	ZL30165GDG2
ZL30166GDG2.WE	ZL30166GDG2	ZL30166GDG2
ZL30167GDG2.WE	ZL30167GDG2	ZL30167GDG2
ZL30168GDG2.WD	ZL30168GDG2	ZL30168GDG2
ZL30169LDF1.UB	ZL30169LDF1	ZL30169LDF1
ZL30169LDG1.UB	ZL30169LDG1	ZL30169LDG1
ZL30174LDG6.E131X	ZL30174LDG6	ZL30174LDG6
ZL30174LDG6.ED	ZL30174LDG6	ZL30174LDG6
ZL30182LFF7.UA	ZL30182LFF7	ZL30182LFF7
ZL30182LFG7.UA	ZL30182LFG7	ZL30182LFG7
ZL30230GGG2.WH	ZL30230GGG2	ZL30230GGG2
ZL30236GGG2.WH	ZL30236GGG2	ZL30236GGG2
ZL30237GGG2.WH	ZL30237GGG2	ZL30237GGG2
ZL30244LFF7.SA	ZL30244LFF7	ZL30244LFF7
ZL30244LFG7.SA	ZL30244LFG7	ZL30244LFG7
ZL30245LFF7.UA	ZL30245LFF7	ZL30245LFF7
ZL30245LFG7.UA	ZL30245LFG7	ZL30245LFG7
ZL30250LDF1.SB	ZL30250LDF1	ZL30250LDF1
ZL30250LDG1.SB	ZL30250LDG1	ZL30250LDG1
ZL30251LDF1.UB	ZL30251LDF1	ZL30251LDF1
ZL30251LDG1.UB	ZL30251LDG1	ZL30251LDG1
ZL30251LDG1Q03F.UBA	ZL30251LDG1Q03F	ZL30251LDG1Q03F
ZL30251LDG1Q04D.UBAX	ZL30251LDG1Q04D	ZL30251LDG1Q04D
ZL30251LDG1Q04D.UBBX	ZL30251LDG1Q04D	ZL30251LDG1Q04D
ZL30252LDF1.SB	ZL30252LDF1	ZL30252LDF1
ZL30252LDG1.SB	ZL30252LDG1	ZL30252LDG1
ZL30253LDF1.UB	ZL30253LDF1	ZL30253LDF1
ZL30253LDG1.UB	ZL30253LDG1	ZL30253LDG1
ZL30254LDF1.UB	ZL30254LDF1	ZL30254LDF1
ZL30254LDG1.UB	ZL30254LDG1	ZL30254LDG1
ZL30255LFF7.UA	ZL30255LFF7	ZL30255LFF7
ZL30255LFG7.UA	ZL30255LFG7	ZL30255LFG7
ZL30256LFG7.QA	ZL30256LFG7	ZL30256LFG7
ZL30256LFG7Q04F.QAAX	ZL30256LFG7Q04F	ZL30256LFG7Q04F
ZL30256LFG7Q04F.QABX	ZL30256LFG7Q04F	ZL30256LFG7Q04F
ZL30256LFG7Q04N.QAAX	ZL30256LFG7Q04N	ZL30256LFG7Q04N
ZL30260LDF1.SB	ZL30260LDF1	ZL30260LDF1
ZL30260LDG1.SB	ZL30260LDG1	ZL30260LDG1
ZL30261LDF1.UB	ZL30261LDF1	ZL30261LDF1

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL30261LDG1.UB	ZL30261LDG1	ZL30261LDG1
ZL30261LDG1Q04Y.UBAX	ZL30261LDG1Q04Y	ZL30261LDG1Q04Y
ZL30262LDF1.SB	ZL30262LDF1	ZL30262LDF1
ZL30262LDG1.SB	ZL30262LDG1	ZL30262LDG1
ZL30263LDF1.UB	ZL30263LDF1	ZL30263LDF1
ZL30263LDG1.UB	ZL30263LDG1	ZL30263LDG1
ZL30263LDG1Q041.UBAX	ZL30263LDG1Q041	ZL30263LDG1Q041
ZL30263LDG1Q044.UBA	ZL30263LDG1Q044	ZL30263LDG1Q044
ZL30263LDG1Q047.UBB	ZL30263LDG1Q047	ZL30263LDG1Q047
ZL30263LDG1Q04C.UBAX	ZL30263LDG1Q04C	ZL30263LDG1Q04C
ZL30263LDG1Q04H.UBAX	ZL30263LDG1Q04H	ZL30263LDG1Q04H
ZL30263LDG1Q04Q.UBAX	ZL30263LDG1Q04Q	ZL30263LDG1Q04Q
ZL30263LDG1Q04W.UBAX	ZL30263LDG1Q04W	ZL30263LDG1Q04W
ZL30263LDG1Q04Z.UBAX	ZL30263LDG1Q04Z	ZL30263LDG1Q04Z
ZL30264LDF1.SB	ZL30264LDF1	ZL30264LDF1
ZL30264LDG1.SB	ZL30264LDG1	ZL30264LDG1
ZL30265LDF1.UB	ZL30265LDF1	ZL30265LDF1
ZL30265LDG1.UB	ZL30265LDG1	ZL30265LDG1
ZL30265LDG1Q040.UBB	ZL30265LDG1Q040	ZL30265LDG1Q040
ZL30265LDG1Q048.UBA	ZL30265LDG1Q048	ZL30265LDG1Q048
ZL30265LDG1Q04V.UBAX	ZL30265LDG1Q04V	ZL30265LDG1Q04V
ZL30266LDF1.SB	ZL30266LDF1	ZL30266LDF1
ZL30266LDG1.SB	ZL30266LDG1	ZL30266LDG1
ZL30267LDF1.UB	ZL30267LDF1	ZL30267LDF1
ZL30267LDG1.UB	ZL30267LDG1	ZL30267LDG1
ZL30267LDG1Q018.UBB	ZL30267LDG1Q018	ZL30267LDG1Q018
ZL30267LDG1Q030.B	ZL30267LDG1Q030	ZL30267LDG1Q030
ZL30267LDG1Q03Z.UBA	ZL30267LDG1Q03Z	ZL30267LDG1Q03Z
ZL30267LDG1Q042.UBA	ZL30267LDG1Q042	ZL30267LDG1Q042
ZL30267LDG1Q046.UBAX	ZL30267LDG1Q046	ZL30267LDG1Q046
ZL30267LDG1Q049.UBA	ZL30267LDG1Q049	ZL30267LDG1Q049
ZL30267LDG1Q04P.UBAX	ZL30267LDG1Q04P	ZL30267LDG1Q04P
ZL30267LDG1Q04S.UBAX	ZL30267LDG1Q04S	ZL30267LDG1Q04S
ZL30281LDF1.UA	ZL30281LDF1	ZL30281LDF1
ZL30281LDG1.UA	ZL30281LDG1	ZL30281LDG1
ZL30282LDF1.UA	ZL30282LDF1	ZL30282LDF1
ZL30282LDG1.UA	ZL30282LDG1	ZL30282LDG1
ZL30342GGG2.WA	ZL30342GGG2	ZL30342GGG2
ZL30343GGG2.WA	ZL30343GGG2	ZL30343GGG2
ZL30347GGG2.WA	ZL30347GGG2	ZL30347GGG2
ZL30361GDG2.WE	ZL30361GDG2	ZL30361GDG2
ZL30362GDG2.WE	ZL30362GDG2	ZL30362GDG2

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL30363GDG2.WE	ZL30363GDG2	ZL30363GDG2
ZL30363GDG2Q03Y.AX	ZL30363GDG2Q03Y	ZL30363GDG2Q03Y
ZL30363GDG2Q04K.WEAX	ZL30363GDG2Q04K	ZL30363GDG2Q04K
ZL30364GDG2.WE	ZL30364GDG2	ZL30364GDG2
ZL30365GDG2.WE	ZL30365GDG2	ZL30365GDG2
ZL30367GDG2.WE	ZL30367GDG2	ZL30367GDG2
ZL30601LDG6.E131X	ZL30601LDG6	ZL30601LDG6
ZL30601LDG6.ED	ZL30601LDG6	ZL30601LDG6
ZL30602LDG6.E131X	ZL30602LDG6	ZL30602LDG6
ZL30602LDG6.ED	ZL30602LDG6	ZL30602LDG6
ZL30603LDG6.E131X	ZL30603LDG6	ZL30603LDG6
ZL30603LDG6.ED	ZL30603LDG6	ZL30603LDG6
ZL30604LDG6.E131X	ZL30604LDG6	ZL30604LDG6
ZL30604LDG6.ED	ZL30604LDG6	ZL30604LDG6
ZL30611LDG6.E131X	ZL30611LDG6	ZL30611LDG6
ZL30611LDG6.ED	ZL30611LDG6	ZL30611LDG6
ZL30612LDG6.E131X	ZL30612LDG6	ZL30612LDG6
ZL30612LDG6.ED	ZL30612LDG6	ZL30612LDG6
ZL30614LDF6.ED	ZL30614LDF6	ZL30614LDF6
ZL30614LDG6.E131X	ZL30614LDG6	ZL30614LDG6
ZL30614LDG6.ED	ZL30614LDG6	ZL30614LDG6
ZL30621LFF7.UA	ZL30621LFF7	ZL30621LFF7
ZL30621LFG7.UA	ZL30621LFG7	ZL30621LFG7
ZL30622LDF1.UB	ZL30622LDF1	ZL30622LDF1
ZL30622LDG1.UB	ZL30622LDG1	ZL30622LDG1
ZL30623LFF7.UA	ZL30623LFF7	ZL30623LFF7
ZL30623LFG7.UA	ZL30623LFG7	ZL30623LFG7
ZL30653LDG6.E102X	ZL30653LDG6	ZL30653LDG6
ZL30671LFG7.QA	ZL30671LFG7	ZL30671LFG7
ZL30672LFG7.QA	ZL30672LFG7	ZL30672LFG7
ZL30673LFG7.Q118X	ZL30673LFG7	ZL30673LFG7
ZL30673LFG7.QA	ZL30673LFG7	ZL30673LFG7
ZL30681LFG7.QA	ZL30681LFG7	ZL30681LFG7
ZL30682LFG7.QA	ZL30682LFG7	ZL30682LFG7
ZL30683LFG7.QA	ZL30683LFG7	ZL30683LFG7
ZL30683LFG7Q03T.Q105X	ZL30683LFG7Q03T	ZL30683LFG7Q03T
ZL30683LFG7Q04B.Q105XAX	ZL30683LFG7Q04B	ZL30683LFG7Q04B
ZL30683LFG7Q04B.QAA	ZL30683LFG7Q04B	ZL30683LFG7Q04B
ZL30701LDG6.E129X	ZL30701LDG6	ZL30701LDG6
ZL30701LDG6.E131X	ZL30701LDG6	ZL30701LDG6
ZL30701LDG6.ED	ZL30701LDG6	ZL30701LDG6
ZL30702LDF6.ED	ZL30702LDF6	ZL30702LDF6

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL30702LDG6.E131X	ZL30702LDG6	ZL30702LDG6
ZL30702LDG6.ED	ZL30702LDG6	ZL30702LDG6
ZL30702LDG6Q02V.E131XAX	ZL30702LDG6Q02V	ZL30702LDG6Q02V
ZL30702LDG6Q02V.EDA	ZL30702LDG6Q02V	ZL30702LDG6Q02V
ZL30702LDG6Q043.EDAX	ZL30702LDG6Q043	ZL30702LDG6Q043
ZL30703LDG6.E131X	ZL30703LDG6	ZL30703LDG6
ZL30703LDG6.ED	ZL30703LDG6	ZL30703LDG6
ZL30704LDF6.ED	ZL30704LDF6	ZL30704LDF6
ZL30704LDG6.E131X	ZL30704LDG6	ZL30704LDG6
ZL30704LDG6.EC	ZL30704LDG6	ZL30704LDG6
ZL30704LDG6.ED	ZL30704LDG6	ZL30704LDG6
ZL30721LFF7.UA	ZL30721LFF7	ZL30721LFF7
ZL30721LFG7.UA	ZL30721LFG7	ZL30721LFG7
ZL30722LDF1.UB	ZL30722LDF1	ZL30722LDF1
ZL30722LDG1.UB	ZL30722LDG1	ZL30722LDG1
ZL30722LDG1Q020	ZL30722LDG1Q020	ZL30722LDG1Q020
ZL30722LDG1Q021	ZL30722LDG1Q021	ZL30722LDG1Q021
ZL30723LFF7.UA	ZL30723LFF7	ZL30723LFF7
ZL30723LFF7Q01N	ZL30723LFF7Q01N	ZL30723LFF7Q01N
ZL30723LFG7.UA	ZL30723LFG7	ZL30723LFG7
ZL30753LDG6.E109X	ZL30753LDG6	ZL30753LDG6
ZL30753LDG6.EA	ZL30753LDG6	ZL30753LDG6
ZL30771LFG7.QA	ZL30771LFG7	ZL30771LFG7
ZL30772LFG7.QA	ZL30772LFG7	ZL30772LFG7
ZL30772LFG7Q04G.QAAX	ZL30772LFG7Q04G	ZL30772LFG7Q04G
ZL30772LFG7Q04J.QAB	ZL30772LFG7Q04J	ZL30772LFG7Q04J
ZL30772LFG7Q04L.QAAX	ZL30772LFG7Q04L	ZL30772LFG7Q04L
ZL30773LFG7.QA	ZL30773LFG7	ZL30773LFG7
ZL30792LFG7.Q100X	ZL30792LFG7	ZL30792LFG7
ZL30803LFG7.Q100X	ZL30803LFG7	ZL30803LFG7
ZL30806LFG7.Q100X	ZL30806LFG7	ZL30806LFG7
ZL30822LFG7.Q100X	ZL30822LFG7	ZL30822LFG7
ZL38040LDF1.BA	ZL38040LDF1	ZL38040LDF1
ZL38040LDG1.BA	ZL38040LDG1	ZL38040LDG1
ZL38042LDF1.BA	ZL38042LDF1	ZL38042LDF1
ZL38042LDG1.BA	ZL38042LDG1	ZL38042LDG1
ZL38042LDG1.BAAAX	ZL38042LDG1	ZL38042LDG1
ZL38050LDF1.BA	ZL38050LDF1	ZL38050LDF1
ZL38050LDG1.BA	ZL38050LDG1	ZL38050LDG1
ZL38050UGB2.BA	ZL38050UGB2	ZL38050UGB2
ZL38051LDF1.BA	ZL38051LDF1	ZL38051LDF1
ZL38051LDG1.BA	ZL38051LDG1	ZL38051LDG1

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL38051UGB2.BA	ZL38051UGB2	ZL38051UGB2
ZL38052LDF1.BA	ZL38052LDF1	ZL38052LDF1
ZL38052LDG1.BA	ZL38052LDG1	ZL38052LDG1
ZL38052LDG1.BAAAX	ZL38052LDG1	ZL38052LDG1
ZL38052UGB2.BA	ZL38052UGB2	ZL38052UGB2
ZL38060LDF1.BA	ZL38060LDF1	ZL38060LDF1
ZL38060LDG1.BA	ZL38060LDG1	ZL38060LDG1
ZL38062LDF1.BA	ZL38062LDF1	ZL38062LDF1
ZL38062LDG1.BA	ZL38062LDG1	ZL38062LDG1
ZL38062UGB2.BA	ZL38062UGB2	ZL38062UGB2
ZL38063LDF1.BA	ZL38063LDF1	ZL38063LDF1
ZL38063LDG1.BA	ZL38063LDG1	ZL38063LDG1
ZL38063LDG1.BAAAX	ZL38063LDG1	ZL38063LDG1
ZL38063UGB2.BA	ZL38063UGB2	ZL38063UGB2
ZL38067LDF1.BA	ZL38067LDF1	ZL38067LDF1
ZL38067LDG1.BA	ZL38067LDG1	ZL38067LDG1
ZL38067LDG1.BAAAX	ZL38067LDG1	ZL38067LDG1
ZL38067UGB2.BA	ZL38067UGB2	ZL38067UGB2
ZL38080LDF1.BA	ZL38080LDF1	ZL38080LDF1
ZL38080LDG1.BA	ZL38080LDG1	ZL38080LDG1
ZL38090LDF1.BB	ZL38090LDF1	ZL38090LDF1
ZL38090LDG1.BAAAX	ZL38090LDG1	ZL38090LDG1
ZL38090LDG1.BB	ZL38090LDG1	ZL38090LDG1
ZL38090UGB2.BB	ZL38090UGB2	ZL38090UGB2
ZL38AMBLDF1.BA	ZL38AMBLDF1	ZL38AMBLDF1
ZL38AMBLDG1.BA	ZL38AMBLDG1	ZL38AMBLDG1
ZL38AMBUGB2.BA	ZL38AMBUGB2	ZL38AMBUGB2
ZL40200LDF1.MB	ZL40200LDF1	ZL40200LDF1
ZL40200LDG1.MB	ZL40200LDG1	ZL40200LDG1
ZL40201LDF1.MB	ZL40201LDF1	ZL40201LDF1
ZL40201LDG1.MB	ZL40201LDG1	ZL40201LDG1
ZL40202LDF1.MB	ZL40202LDF1	ZL40202LDF1
ZL40202LDG1.MB	ZL40202LDG1	ZL40202LDG1
ZL40203LDF1.MB	ZL40203LDF1	ZL40203LDF1
ZL40203LDG1.MB	ZL40203LDG1	ZL40203LDG1
ZL40204LDF1.MB	ZL40204LDF1	ZL40204LDF1
ZL40204LDG1.MB	ZL40204LDG1	ZL40204LDG1
ZL40205LDF1.MB	ZL40205LDF1	ZL40205LDF1
ZL40205LDG1.MB	ZL40205LDG1	ZL40205LDG1
ZL40206LDF1.MB	ZL40206LDF1	ZL40206LDF1
ZL40206LDG1.MB	ZL40206LDG1	ZL40206LDG1
ZL40207LDF1.MB	ZL40207LDF1	ZL40207LDF1

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL40207LDG1.MB	ZL40207LDG1	ZL40207LDG1
ZL40208LDF1.MB	ZL40208LDF1	ZL40208LDF1
ZL40208LDG1.MB	ZL40208LDG1	ZL40208LDG1
ZL40209LDF1.MB	ZL40209LDF1	ZL40209LDF1
ZL40209LDG1.MB	ZL40209LDG1	ZL40209LDG1
ZL40210LDF1.MB	ZL40210LDF1	ZL40210LDF1
ZL40210LDG1.MB	ZL40210LDG1	ZL40210LDG1
ZL40211LDF1.MB	ZL40211LDF1	ZL40211LDF1
ZL40211LDG1.MB	ZL40211LDG1	ZL40211LDG1
ZL40212LDF1.MC	ZL40212LDF1	ZL40212LDF1
ZL40212LDG1.MC	ZL40212LDG1	ZL40212LDG1
ZL40213LDF1.MC	ZL40213LDF1	ZL40213LDF1
ZL40213LDG1.MC	ZL40213LDG1	ZL40213LDG1
ZL40214LDF1.MC	ZL40214LDF1	ZL40214LDF1
ZL40214LDG1.MC	ZL40214LDG1	ZL40214LDG1
ZL40215LDF1.MC	ZL40215LDF1	ZL40215LDF1
ZL40215LDG1.MC	ZL40215LDG1	ZL40215LDG1
ZL40216LDF1.MC	ZL40216LDF1	ZL40216LDF1
ZL40216LDG1.MC	ZL40216LDG1	ZL40216LDG1
ZL40217LDF1.MC	ZL40217LDF1	ZL40217LDF1
ZL40217LDG1.MC	ZL40217LDG1	ZL40217LDG1
ZL40218LDF1.MC	ZL40218LDF1	ZL40218LDF1
ZL40218LDG1.MC	ZL40218LDG1	ZL40218LDG1
ZL40219LDF1.MC	ZL40219LDF1	ZL40219LDF1
ZL40219LDG1.MC	ZL40219LDG1	ZL40219LDG1
ZL40220LDF1.MC	ZL40220LDF1	ZL40220LDF1
ZL40220LDG1.MC	ZL40220LDG1	ZL40220LDG1
ZL40221LDF1.MC	ZL40221LDF1	ZL40221LDF1
ZL40221LDG1.MC	ZL40221LDG1	ZL40221LDG1
ZL40222LDF1.MC	ZL40222LDF1	ZL40222LDF1
ZL40222LDG1.MC	ZL40222LDG1	ZL40222LDG1
ZL40223LDF1.MC	ZL40223LDF1	ZL40223LDF1
ZL40223LDG1.MC	ZL40223LDG1	ZL40223LDG1
ZL40224LDF1.MB	ZL40224LDF1	ZL40224LDF1
ZL40224LDG1.MB	ZL40224LDG1	ZL40224LDG1
ZL40225LDF1.MB	ZL40225LDF1	ZL40225LDF1
ZL40225LDG1.MB	ZL40225LDG1	ZL40225LDG1
ZL40226LDF1.MC	ZL40226LDF1	ZL40226LDF1
ZL40226LDG1.MC	ZL40226LDG1	ZL40226LDG1
ZL40227LDF1.MC	ZL40227LDF1	ZL40227LDF1
ZL40227LDG1.MC	ZL40227LDG1	ZL40227LDG1
ZL40230LDF1.MB	ZL40230LDF1	ZL40230LDF1

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL40230LDG1.MB	ZL40230LDG1	ZL40230LDG1
ZL40231LDF1.MB	ZL40231LDF1	ZL40231LDF1
ZL40231LDG1.MB	ZL40231LDG1	ZL40231LDG1
ZL40234LDF1.MB	ZL40234LDF1	ZL40234LDF1
ZL40234LDG1.MB	ZL40234LDG1	ZL40234LDG1
ZL40235LDF1.MB	ZL40235LDF1	ZL40235LDF1
ZL40235LDG1.MB	ZL40235LDG1	ZL40235LDG1
ZL40240LDF1.MA	ZL40240LDF1	ZL40240LDF1
ZL40240LDG1.MA	ZL40240LDG1	ZL40240LDG1
ZL40241LDF1.MA	ZL40241LDF1	ZL40241LDF1
ZL40241LDG1.MA	ZL40241LDG1	ZL40241LDG1
ZL40250LDF1.SB	ZL40250LDF1	ZL40250LDF1
ZL40250LDG1.SB	ZL40250LDG1	ZL40250LDG1
ZL40251LDF1.UB	ZL40251LDF1	ZL40251LDF1
ZL40251LDG1.UB	ZL40251LDG1	ZL40251LDG1
ZL40252LDF1.SB	ZL40252LDF1	ZL40252LDF1
ZL40252LDG1.SB	ZL40252LDG1	ZL40252LDG1
ZL40253LDF1.UB	ZL40253LDF1	ZL40253LDF1
ZL40253LDG1.UB	ZL40253LDG1	ZL40253LDG1
ZL40253LDG1Q04T.UBAX	ZL40253LDG1Q04T	ZL40253LDG1Q04T
ZL40255LDF1.UA	ZL40255LDF1	ZL40255LDF1
ZL40255LDG1.UA	ZL40255LDG1	ZL40255LDG1
ZL40260LDF1.MC	ZL40260LDF1	ZL40260LDF1
ZL40260LDG1.MC	ZL40260LDG1	ZL40260LDG1
ZL40260QGF1.MC	ZL40260QGF1	ZL40260QGF1
ZL40260QGG1.MC	ZL40260QGG1	ZL40260QGG1
ZL40262LDG1.MAAAX	ZL40262LDG1	ZL40262LDG1
ZL40264LDG1.MAAAX	ZL40264LDG1	ZL40264LDG1
ZL40292LDG1.TA	ZL40292LDG1	ZL40292LDG1
ZL40292LDG1.TACAX	ZL40292LDG1	ZL40292LDG1
ZL79124GDG2.MD	ZL79124GDG2	ZL79124GDG2
ZL792388GDG2.MF	ZL792388GDG2	ZL792388GDG2
ZL792588GDG2.MB	ZL792588GDG2	ZL792588GDG2
ZL80018GGG2.WH	ZL80018GGG2	ZL80018GGG2
ZL80020GDG2.WD	ZL80020GDG2	ZL80020GDG2
ZL80025GGG2.WA	ZL80025GGG2	ZL80025GGG2
ZL80026LDF1.BA	ZL80026LDF1	ZL80026LDF1
ZL80026LDG1.BA	ZL80026LDG1	ZL80026LDG1
ZL80027LDF1.BA	ZL80027LDF1	ZL80027LDF1
ZL80027LDG1.BA	ZL80027LDG1	ZL80027LDG1
ZL80027UGB2.BA	ZL80027UGB2	ZL80027UGB2
ZL80029LDG6.E131X	ZL80029LDG6	ZL80029LDG6

GBNG-20VJLK817 - CCB 3765 Final Notice: Implement Catalog Part Number (CPN) convention changes to selected Microsemi (LCLD, VPT, TIM and WIFI) products.

Affected Catalog Part Number (CPN)

PCN_GBNG-20VJLK817_Affected_CPN		
Existing Microsemi (LCLD, VPT, TIM and WIFI) Catalog Part numbers (CPN) - if you were ordering the part in column A or B which are the same:		New/Replacement Catalog Part number (CPN) - as of May 1, 2019 you will be required to order the part number as listed in column C:
ZL80029LDG6.ED	ZL80029LDG6	ZL80029LDG6
ZL80035LFG7.QA	ZL80035LFG7	ZL80035LFG7
ZL80062LFG7.QB	ZL80062LFG7	ZL80062LFG7
ZL80143GGG2.WA	ZL80143GGG2	ZL80143GGG2
ZL80267LDG1.U103X	ZL80267LDG1	ZL80267LDG1
ZL81000GGG2.TA	ZL81000GGG2	ZL81000GGG2
ZL88109LDG1.AB	ZL88109LDG1	ZL88109LDG1
ZL88701LDG1.AE	ZL88701LDG1	ZL88701LDG1
ZL88702LDG1.AE	ZL88702LDG1	ZL88702LDG1
LE9632RQCT.AB	LE9632RQCT	LE9632RQCT
LE9652PQCT.AD	LE9652PQCT	LE9652PQCT
ZL88107LDF1.AD	ZL88107LDF1	ZL88107LDF1
LE9672WQCT.AC	LE9672WQCT	LE9672WQCT
ZL88103LDF1.AE	ZL88103LDF1	ZL88103LDF1
ZL88801LDG1.AC	ZL88801LDG1	ZL88801LDG1
LE9622RQCT.AB	LE9622RQCT	LE9622RQCT
LE9662WQCT.AC	LE9662WQCT	LE9662WQCT
ZL88601LDF1.AE	ZL88601LDF1	ZL88601LDF1
ZL88105LDF1.AC	ZL88105LDF1	ZL88105LDF1
ZL88109LDF1.AB	ZL88109LDF1	ZL88109LDF1
ZL88702LDF1.AD	ZL88702LDF1	ZL88702LDF1
ZL88701LDF1.AE	ZL88701LDF1	ZL88701LDF1
ZL88702LDF1.AE	ZL88702LDF1	ZL88702LDF1
ZL88602LDF1.AE	ZL88602LDF1	ZL88602LDF1
ZL88801LDF1.AC	ZL88801LDF1	ZL88801LDF1
ZLJ6080UAH.JA	ZLJ6080UAH	ZLJ6080UAH