

Issue Date: February 13th, 2020

Dear Valued Customer,

This notice is to inform you of the obsolescence of a select item that you have purchased from Littelfuse.

Description of the Change:

- Littelfuse has obsoleted and will no longer support production or service of 97859-R.

Reason for The Change:

- This part has not been used in an active finished good for over two years and there are insufficient annual sales to continue support of tooling and production of this component.

Effective Date of the Change:

- This obsolescence is effective immediately.


What You Need to Do:

- There is no stock of this part number, and therefore a last-time-buy cannot be supported.

For any questions, please feel free to reach out to either your Littelfuse Customer Service Representative or Inside Sales Representative.

We appreciate your continued partnership and business.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products