



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: I-09-03 Last Buy Deadline for Submission of Order: 7-Dec-2010

Issue Date: 7-Dec-2009 Last Eligible Ship Date: 7-Mar-2011

Contact: Matt Jones
 Title: Marketing Manager - SSP Products
 Phone #: 408-360-5622
 Fax #: 408-360-1748
 E-mail: Matt.Jones@idt.com

PRODUCT(S) AFFECTED: ATTACHMENT Yes No

(List Replacement Part #(s), if any)

Selected SSP part will be discontinued. Refer to Attachment I for discontinued part# list.

REASON FOR DISCONTINUANCE:

- Replace slower speed with faster speed offerings Other: _____
- Obsolete Fab Technology / Process _____
- Obsolete Assembly Technology / Process _____
- Obsolete Package / Material _____
- Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____

Name/Date: _____ Phone#: _____

Title: _____ Fax#: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: I-09-03

Affected Part Number

Discontinued Part#	Discontinued Part#	Discontinued Part#	Discontinued Part#
79RC32T332-100DH	79RC32T355-100DH	79RC32V332-100DHGI	79RC32V334-100BB
79RC32T332-100DH8	79RC32T355-100DH8	79RC32V332-100DHGI8	79RC32V334-100BB8
79RC32T332-100DHI	79RC32T355-100DHG	79RC32V332-100DHI	79RC32V334-100BBG
79RC32T332-100DHI8	79RC32T355-100DHG8	79RC32V332-100DHI8	79RC32V334-100BBG8
79RC32T332-133DH	79RC32T355-100DHGI	79RC32V332-133DH	79RC32V334-100BBGI
79RC32T332-133DH8	79RC32T355-100DHGI8	79RC32V332-133DH8	79RC32V334-100BBGI8
79RC32T332-133DHI	79RC32T355-100DHI	79RC32V332-133DHG	79RC32V334-100BBI
79RC32T332-133DHI8	79RC32T355-100DHI8	79RC32V332-133DHG8	79RC32V334-100BBI8
79RC32T332-150DH	79RC32T355-133DH	79RC32V332-133DHGI	79RC32V334-133BB
79RC32T332-150DH8	79RC32T355-133DH8	79RC32V332-133DHGI8	79RC32V334-133BB8
79RC32T333-100DH	79RC32T355-133DHG	79RC32V332-133DHI	79RC32V334-133BBG
79RC32T333-100DH8	79RC32T355-133DHG8	79RC32V332-133DHI8	79RC32V334-133BBG8
79RC32T333-100DHI	79RC32T355-133DHGI	79RC32V332-150DH	79RC32V334-133BBGI
79RC32T333-100DHI8	79RC32T355-133DHGI8	79RC32V332-150DH8	79RC32V334-133BBGI8
79RC32T333-133DH	79RC32T355-133DHI	79RC32V332-150DHG	79RC32V334-133BBI
79RC32T333-133DH8	79RC32T355-133DHI8	79RC32V332-150DHG8	79RC32V334-133BBI8
79RC32T333-133DHI	79RC32T355-150DH	79RC32V332-150DHGI	79RC32V334-150BB
79RC32T333-133DHI8	79RC32T355-150DH8	79RC32V332-150DHGI8	79RC32V334-150BB8
79RC32T333-150DH	79RC32T355-150DHG	79RC32V332-150DHI	79RC32V334-150BBG
79RC32T333-150DH8	79RC32T355-150DHG8	79RC32V332-150DHI8	79RC32V334-150BBG8
79RC32T336-150BC	79RC32T355-150DHGI	79RC32V333-100DH	79RC32V334-150BBGI
79RC32T336-150BC8	79RC32T355-150DHGI8	79RC32V333-100DH8	79RC32V334-150BBGI8
79RC32T336-150BCI	79RC32T355-150DHI	79RC32V333-100DHG	79RC32V334-150BBI
79RC32T336-150BCI8	79RC32T355-150DHI8	79RC32V333-100DHG8	79RC32V334-150BBI8
79RC32T336-150BCG	79RC32T355-180DH	79RC32V333-100DHGI	
79RC32T336-150BCG8	79RC32T355-180DH8	79RC32V333-100DHGI8	
79RC32T336-150BCGI	79RC32T355-180DHG	79RC32V333-100DHI	
79RC32T336-150BCGI8	79RC32T355-180DHG8	79RC32V333-100DHI8	
79RC32T351-100DH	79RC32T355-180DHGI	79RC32V333-133DH	
79RC32T351-100DH8	79RC32T355-180DHGI8	79RC32V333-133DH8	
79RC32T351-100DHG	79RC32T355-180DHI	79RC32V333-133DHG	
79RC32T351-100DHG8	79RC32T355-180DHI8	79RC32V333-133DHG8	
79RC32T351-100DHGI	79RC32T365-150BC	79RC32V333-133DHGI	
79RC32T351-100DHGI8	79RC32T365-150BC8	79RC32V333-133DHGI8	
79RC32T351-100DHI	79RC32T365-150BCG	79RC32V333-133DHI	
79RC32T351-100DHI8	79RC32T365-150BCG8	79RC32V333-133DHI8	
79RC32T351-133DH	79RC32T365-150BCGI	79RC32V333-150DH	
79RC32T351-133DH8	79RC32T365-150BCGI8	79RC32V333-150DH8	
79RC32T351-133DHG	79RC32T365-150BCI	79RC32V333-150DHG	
79RC32T351-133DHG8	79RC32T365-150BCI8	79RC32V333-150DHG8	
79RC32T351-133DHGI	79RC32V332-100DH	79RC32V333-150DHGI	
79RC32T351-133DHGI8	79RC32V332-100DH8	79RC32V333-150DHGI8	
79RC32T351-133DHI	79RC32V332-100DHG	79RC32V333-150DHI	
79RC32T351-133DHI8	79RC32V332-100DHG8	79RC32V333-150DHI8	