

## Introduction:

Effective immediately, Advantech is announcing the Manufacture Discontinue and End of Life of the following part numbers. Customers who purchase this model should review current and future needs for this product to determine whether additional purchases of these products are required or migrate to replacement model if possible, before the Manufacture Discontinue takes effect.

## Definition:

Milestone	Definition	Date
Phase Out Announce Date:	The date that this Announcement takes effect.	<b>February 13th, 2019</b>
Last Time Buy Date:	The last date to order the product through Advantech. The product is no longer for sale after this date.	<b>November 1st, 2019</b>
Last Shipment Date :	The last date of shipment from Advantech Non-cancel non-return order is required for shipment scheduled to be shipped after the Last-time-buy date.	<b>February 1st, 2020</b>

## Product Part Numbers Affected by This Announcement:

EOL product Part number	LTB	Applicable Replacement Model	Replacement Product Description
ARK-2150L-S4A1E	11/01/2019	ARK-2250L-U3A1E	Intel Core i3 Fanless Box Computer
ARK-2150L-S6A1E	11/01/2019	ARK-2250L-U3A1E	Intel Core i3 Fanless Box Computer
ARK-2150L-S7A1E	11/01/2019	ARK-2250L-U6A1E	Intel Core i7 Fanless Box Computer

## **ORDER FULLFILLMENT AFTER PRODUCT PHASED OUT:**

When a product is going to be phase out, customers will be given a notice to place their final order to be delivered before the last shipment date. Here is an option to extend the shipment for 12 months after the last buy date by completing these two processes before the last buy date.

1. If there are parts to be obsolete customer needs to buys through Advantech the parts and have Advantech hold them in inventory as “customer owned inventory”. Please contact Advantech Sales Rep. for the actual cost.
2. After the last buy date the product will be made per order. Customer is required to places a non--cancelable, non-returnable order to be delivered in 12 months at minimum 100 pcs / shipment for board level products. In some cases due to the limited supply of material or manufacturing process change, this service might not be available. Please confirm with Advantech Sales Rep. before preceding the above process.