


Product Obsolescence Memo

INDUCTIVE COMPONENTS



October 30, 2018

Bourns® Model 74F686AP-3%-RC and 74F686AP-3%-TR-RC Axial Lead Inductors to be Discontinued

Bourns® Model 74F686AP-3%-RC and 74F686AP-3%-TR-RC Axial Lead Inductors will be discontinued. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part numbers are available.

Obsolete Part Numbers:

74F686AP-3%-RC
74F686AP-3%-TR-RC

Please plan for the following deadlines:

*Last time buy date: **February 28, 2019***

*Last time ship date: **May 31, 2019***

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).