



## Customer Information Notification

201904034I

**Issue Date:** 27-Jul-2019  
**Effective Date:** 28-Jul-2019

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online

**This notice is NXP Company Proprietary.**



# QUALITY

### Change Category

- |  |   |  |   |  |
|--|---|--|---|--|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process   | <input type="checkbox"/> Product Marking           | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                                    |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification  | <input type="checkbox"/> Test Process   | <input type="checkbox"/> Errata                                    |
| <input type="checkbox"/> Wafer Fab Location  | <input type="checkbox"/> Assembly Location  | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input checked="" type="checkbox"/> Electrical spec./Test coverage |
| <input type="checkbox"/> Firmware            | <input type="checkbox"/> Other              |  |   |  |

**PF1510 Data Sheet Update to Rev 2.0**

### Description

NXP Semiconductors announces a data sheet update to revision 2.0 for the PF1510 devices associated with this notification. The revision history included in the updated document provides a detailed description of the changes.

The PF1510 data sheet revision 2.0 is attached to this notice, and can be found at:  
<https://www.nxp.com/docs/en/data-sheet/PF1510.pdf>

### Reason

The data sheet has been updated to correct errors and / or provide additional technical clarification on some device features.

### Identification of Affected Products

Product identification does not change

### Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

### Data Sheet Revision

A new datasheet will be issued

### Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

**Name** Sean Liu  
**Position** Applications Engineer  
**e-mail address** sean.liu@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

### About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[NXP | Privacy Policy | Terms of Use](#)

NXP Semiconductors  
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	Changed Part 12NC	Changed Part Number	Changed Part Description	Package Outline	Package Name	Status	Product Line
MC34PF1510A6EPR2	935371917528	MC34PF1510A6EPR2	PF1510	SOT1369-4	HVQFN40	RFS	Safety & Power Mgmt
MC32PF1510A3EPR2	935371715528	MC32PF1510A3EPR2	PF1510	SOT1369-4	HVQFN40	RFS	Safety & Power Mgmt
MC34PF1510A4EPR2	935371922528	MC34PF1510A4EPR2	PF1510	SOT1369-4	HVQFN40	RFS	Safety & Power Mgmt
MC34PF1510A1EPR2	935371928528	MC34PF1510A1EPR2	PF1510	SOT1369-4	HVQFN40	RFS	Safety & Power Mgmt
MC32PF1510A1EPR2	935371912528	MC32PF1510A1EPR2	PF1510	SOT1369-4	HVQFN40	RFS	Safety & Power Mgmt